TSD File inventory index

	Date: _	and and	25.	2000
	- <i>0</i>	: 1	. 1	4
. Pa	Initial:	Chile	MUL	1

		•	
Fectility Name:		(a) file da	
Facility Identification Standor:			
A.1 General Correspondence		B.2 Permit Docket (B.1.2)	
A.2 Part A / Interim Status	V	.1 Correspondence	
.1 Correspondence		.2 All Other Permitting Documents (Not Part of the ARA)	
.2 Notification and Acknowledgment		C.1 Compliance - (Inspection Reports)	i de la company
.3 Part A Application and Amendments		C.2 Compliance/Enforcement	
4 Financial Insurance (Sudden, Non Sudden)	1	.1 Land Disposal Restriction Notifications	
.5 Change Under Interim Status Requests		.2 Import/Export Notifications	
.6 Annual and Blennial Reports		C.3 FOIA Exemptions - Non-Releasable Documents	
A.3 Groundwater Monitoring	•	D.1 Corrective Action/Facility Assessment	A. Service
.1 Correspondence		.1 RFA Comespondence	
.2 Reports		.2 Background Reports, Supporting Docs and Studies	Harris Market Ma
A.4 Closure/Post Closure		.3 State Prelim. Investigation Memos	
. 1. Correspondence		.4 RFA Reports	^
.2 Closure/Post Closure Plans, Certificates, etc		D. 2 Corrective Action/Facility Investigation	
A.5 Ambient Air Monitoring		.1 RFI Correspondence	
.1 Correspondence		.2 RFI Workplan	
.2 Reports		.3 RFI Program Reports and Oversight	
B.1 Administrative Record		.4 RFi Draft /Final Report	

Tell

.5 RFI QAPP		.6 CMI QAPP	
.6 RFI QAPP Correspondence		.7 Lab Data, Soil-Sampling/Groundwater	1
.7 Lab Data, Soil-Sampling/Groundwater		.8 Progress Reports	. ,
.8 RFI Progress Reports		D.5 Corrective Action/Enforcement	
.9 Interim Measures Correspondence		.1 Administrative Record 3008(h) Order	
.10 Interim Measures Workplan and Reports		.2 Other Non-AR Documents	
).3 Corrective Action/Remediation Study		E. Bollers and Industrial Furnaces (BIF)	
.1 CMS Correspondence		.1 Correspondence	
.2 Interim Measures		.2 Reports	
.3 CMS Workplan		F.1 Imagery/Special Studies (Videos, Photos, Disks, Maps, Blueprints, Drawings, and Other Not Oversized Special Materials.)	Ŷ
.4 CMS Draft/Final Report	- •		
.5 Stabilization		.1 Human/Ecological Assessment	1
.8 CMS Progress Reports		.2 Compliance and Enforcement	• ;
.7 Lab Data, Soil-Sampling/Groundwater		.3 Enforcement Confidential	
D.4 Corrective Action Remediation Implementati	lon	.4 Ecological - Administrative Record	
.1 CMI Correspondence		.5 Permitting	3
.2 CMI Workplan		.6 Corrective Action/Remediation Study	
.3 CMI Program Reports and Oversight		.7 Corrective Action Remediation Implementation	
.4 CMI Draft/Final Reports		.8 Endangered Species Act	
.5 CMI QAPP		.9 Environmental Justice	

MOID: 113	ausimitsi Fed	al to de il	Kiroba anii K	spors.`					
Commer	nts: Dogun	unto	bost	Mes. D.	nduntu	d fol	t yw	selete	de i

,



ACKNOWLEDGEMENT OF NOTIFICATION OF HAZARDOUS WASTE ACTIVITY (VERIFICATION)

This is to acknowledge that you have filed a Notification of Hazardous Waste Activity for the installation located at the address shown in the box below to comply with Section 3010 of the Resource Conservation and Recovery Act (RCRA). Your EPA Identification Number for that installation appears in the box below. The EPA Identification Number must be included on all shipping manifests for transporting hazardous wastes; on all Annual Reports that generators of hazardous waste, and owners and operators of hazardous waste treatment, storage and disposal facilities must file with EPA; on all applications for a Federal Hazardous Waste Permit; and other hazardous waste management reports and documents required under Subtitle C of RCRA.

EDA E 9700 429 (4 90)	-	00/28/84			
INSTALLATION ADDRESS		1919 STANLEY STRE	to the second se		600 8 S
		1919 STANLEY ST NORTHBROOK		IL	60062
EPA I.D. NUMBER	*	ILD005180195 DEUBLIN COMPANY	REACK	NOWLE	DGEMENT

EPA Form 8700-12B (4-80)

09/28/81

practers/inch) in the unshaded areas only.

Please print or type with ELITE type (

Form Approved OMB No. 158-S79016

GSA No. 0246-EPA-OT

IX. DESCRIPTION OF HAZA	RDOUS WASTES (con	tinued from front)				
A. HAZARDOUS WASTES FROM waste from non-specific source				FR Part 261.31 for e	ach listed hazardous	
1 33 - 25 7	2 13 - 26 8	3 26 9	6 23 - 26 10	23 - 26	5 23 - 76 12	Aper
23 - 26 2 23 - 26 2	20 - 26 23 23	26	13 - 26 -	23 - 26	23 - 26	^^
B. HAZARDOUS WASTES FROM specific industrial sources your i				E 201,32 for each list	ed nazardous waste tro	m >
13 23 - 7 - 26 19	14 3 - 48 20	15	16	17 23 - 26 23	18 23 - 26 24	
23 - 25	3 - 16 23	- 86 27	20 - 26	29	39 - 26	
C. COMMERCIAL CHEMICAL PR				23 26 10 CFR Part 261.33	zs - ze for each chemical sub-	
stance your installation handles	which may be a hazardous	waste. Use addition	al sheets if necessary.	35	36	
4226	3 - 26 23	7 26	3 - 26	22 - 25	23 - 26	
23 - 36	38	26	23 - 26	23 - 26	23 - 36	
23 - 26	3 - 26 23	45	35 - 25	23 - 25	23 - 26	
D. LISTED INFECTIOUS WASTE hospitals, medical and research					om hospitals, veterinar	Y I
49	56	51	52	53	54	
E. CHARACTERISTICS OF NON- hazardous wastes your installati				ing to the characteris	tics of non-listed	
☐1. IGNITABLE (D001)	∏z. cor (pagz)	ROSIVE	☐3. REACTIVE (D003)]4. TOXIC 000)	
X, CERTIFICATION						20
I certify under penalty of leastached documents, and the I believe that the submitted mitting false information, inc	it based on my inquiry information is true, ac	of those individu curate, and compl	als immediately resp ete. I am aware that	onsible for obtain	ing the information,	້ ຕໍ່
SIGNATURE SAL	Z.	JACK E	TITLE (type or print) , FALLS MANAGE/	2	bate signed 8-26-80	
EPA Form 8700-12 (6-80) REVE	PSE					

CONTRACTOR CONTRACTOR

MAY - 2 1984

Carl L. Birkenstock, Vice President Deublin Company 1919 Stanley Street Northbrook, Illinois 60062

> Withdrawal of Part A Permit Application ILD 005180195

Dear Mr. Birkenstock:

The U.S. Environmental Protection Agency has reviewed your request to withdraw your RCRA Part A permit application. On the basis of the information you provided, we determined that your operation included treatment, storage, or disposal of hazardous waste subject to 35 Ill. Adm. Code Part 725. Therefore, a closure plan must be submitted directly to Permit Section, Division of Land Pollution Control, Illinois Environmental Protection Agency, 2200 Churchill Road, Springfield, Illinois 62706. Requirements for closure are found at 35 Ill. Adm. Code Part 725. Questions on closure should be directed to Illinois EPA at the above address.

Thank you for your cooperation in this matter. Sincerely,

Robert L. Stone State Implementation Officer

cc: Larry Eastep, IEPA Bill Radlinski, IEPA

bcc: Lisa Pierard, RAIU Chuck Lewis, GMCU

5HW-12:B.STONE:ad: 5/1/84

WMD WMB STU #1 DIRECTOR CHIEF CHIEF



June 8, 1983

U.S.E.P.A. Region V 230 South Dearborn St. Chicago, Il. 60604

Attn: 5 HW-13

Subject: Request for Information - Small Quantity Generator

Deublin Company ILD 005-180-195 PAINRS >

Dear Sirs:

Due to a misunderstanding on my part (waiting for information on shipping) we have accumulated approximately a 14 months total of waste material. We are in the process of having this material disposed of now (recycling and disposal).

When this is accomplished we will be in compliance in all regards to qualify as a "Small Quantity Generator." This is according to the best of my ability to interpret the E.P.A. standards.

Per the above, I request withdrawal of our application for permits and ask that you advise me accordingly for my future activities. Thank you for any assistance you may give.

Respectfully,


J. E. Falls Plant Manager

Certified in accordance with 40 CFR Part 270.11

Karl L. Birkenstock

Vice President

js







UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION V

230 SOUTH DEARBORN ST. CHICAGO, ILLINOIS 60604

REPLY TO ATTENTION OF: 5HW-13

MAY 2 6 1983

Mr. Jack E. Falls, Plant Manager Deublin Company 1919 Stanley Street Northbrook, Illinois 60062

RE: Request for Information--Hazardous Waste Permit

Review (Small Quantity Generator)

FACILITY: NAME: Deublin Company U.S. EPA ID NO.: ILD 005 780 195

Dear Mr. Falls:

This is to acknowledge that the United States Environmental Protection Agency has completed reviewing your Part A Hazardous Waste Permit Application. Our review indicates your facility may not require a permit under §3005 of the Resource Conservation and Recovery Act; however, further clarification is needed.

Based on the information submitted, your facility appears to qualify for the small quantity generator exclusion as defined in 40 CFR Part 261.5 (enclosed). Please review these requirements to verify that your facility qualifies for the small quantity generator exclusion from November 19, 1980, to the present. If it does, a permit is not required, and you should withdraw your permit application. Please submit your determination in writing, signed and certified by an authorized person in accordance with 40 CFR Part 270.11 (enclosed), fied by an authorized person in accordance with 40 CFR Part 270.11 (enclosed), requesting that your application be withdrawn. If at any time, since November 19, 1980, your operation (1) did not qualify for the special requirements for 19, 1980, your operation (1) did not qualify for the special requirements for storage, or disposal of hazardous wastes, and (2) included treatment, storage, or disposal of hazardous waste subject to 40 CFR Part 265, a closure plan must be filed with the withdrawal request. Requirements for closure are found at 40 CFR Part 265 Subpart G.

If your review indicates that a permit is required, but certain information on your application is incorrect, please submit a revised Part A with the appropriate changes to this Regional Office. If no response is received in this office within 30 days, we will assume your facility requires a permit. Accordingly, we will continue to process your application.

Please do not hesitate to contact the Technical, Permits, and Compliance Section at (312) 353-2197 for assistance, if you have any questions. Please refer to "Request for Information--Small Quantity Generator," in all correspondence on this matter.


Sincerely, yours,

Karl J. Klepitsch. Jr., Chief Waste Hanggement Branch

Enclosures/cc: Karl L. Birkenstock, Vice President

Please print or type in the (fill—in areas are spaced for FORM	or elite type, i.e., 12 characters u:		DTECTION AGENCY	Form Approved	OMB No. 158-R0175
GENERAL LABEL ITEMS	ra -	Consolidated Perm the "General Instructi	its Program	If a preprinted	O 5 1 8 O 1 9 5 D TA 18 18 TAL INSTRUCTIONS label has been provided, affix
PA I.D. NUMBER		5		ation carefully; through it and	ated space. Review the inform- if any of it is incorrect, cross enter the correct data in the -in area below. Also, if any of
V. FACILITY V. MAILING ADDRE	DEUBLIN COMP 1919 STANLEY NORTHBROOK,	ST		the preprinted left of the lak that should ap proper fill—in	data is absent (the area to the pel space lists the information pear), please provide it in the area(s) below. If the label is
VI. FACILITY LOCATION	1919 STAMLE MORTHBROOK:			Items I, III, \ must be comp items if no lab the instruction tions and for	correct, you need not complete /, and VI (except VI-B which leted regardless). Complete all let has been provided. Refer to ns for detailed item descrip- the legal authorizations under
II. POLLUTANT CHAR.				which this data	A
questions, you must su	nplete A through J to determ bmit this form and the supplo m is attached. If you answer t requirements; see Section C o	emental form listed in "no" to each questio	n the parenthesis followin n, you need not submit a	g the question, Mark "X" i ny of these forms, You may	n the box in the third column y answer "no" if your activity
	FIC QUESTIONS	MARK'X' YES NO ATTAC		ECIFIC QUESTIONS	MARK X YES NO FORM ATTACHES
which results in a (FORM 2A)	discharge to waters of the U	J.S.? X	include a conce aquatic animal discharge to wate	intrated animal feeding of production facility which ers of the U.S.? (FORM 2B	peration or results in a 1 19 20 21
to waters of the U A or B above? (FOF		ed in A	in A or B above waters of the U.	ed facility (other than those) b) which will result in a d S.? (FORM 2D) you inject at this facility is	lischarge (0
hazardous wastes? (A 29 30	municipal efflue taining, within	ent below the lowermost st one quarter mile of the arces of drinking water? (F	tratum con-
water or other fluid in connection with duction, inject flui	inject at this facility any prod is which are brought to the sur conventional oil or natural gas ds used for enhanced recover ir inject fluids for storage of li	rface pro- v of	cial processes su process, solution tion of fossil fu	you inject at this facility fluch as mining of sulfur by mining of minerals, in siel, or recovery of geothern	the Frasch itu combus-
hydrocarbons? (FO I. Is this facility a proper of the 28 and	RM 4) oposed stationary source whi ustrial categories listed in th	34 38 36 ch is e in- 4 /	J. Is this facility a NOT one of the	a proposed stationary sour e 28 industrial categories l I which will potentially em	isted in the
per year of any a	ch will potentially emit 100 if pollutant regulated under may affect or be located i ORM 5)	the //\	per year of any	air pollutant regulated und y affect or be located in an	er the Clean / \
III. NAME OF FACILIT					
IV. FACILITY CONTAC	A. NAME & TITLE (ld	ist, first, & title)		B, PHONE fatea co	de & no.)
FALLS .	IACK E.	PLANTA	1GR.	3/2 272	6060
V. FACILITY MAILING	ADDRESS A. STREET OR	P.O. BOX			
3 15 16	B. CITY OR TOWN		C.STATE D.	A1 ZIP CODE	
4 15 16			40 41 41 37	1 1 1 1 1 1 1 1 1 1	
VI, FACILITY LOCATION	IN PREET, ROUTE NO. OR OTH	HER SPECIFIC IDEN	TIFIER		
15 16	B. COUNTY NAME			45	The second secon
COOK	C. CITY OR TOWN		70 D.STATE E.	ZIP CODE F. COUNT	Y CODE
6 , , , , , , , , , , , , , , , , , , ,		r r r r r r r		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	<u>wn</u>)
EPA Form 3510-1 (6-80)		The state of the s	08 1990	and the second	CONTINUE ON REVERSE

CONTINUED FROM THE FRONT VII. SIC CODES (4-digit, in order of priority)		<u> </u>	
A FIRST S 3490 (specify) MISC MEGD, ITEMS	6 (spe	B. SECOND scify)	
C. THIRD (specify) 7 16 16 - 19		р, Fourth ecify)	
VIII. OPERATOR INFORMATION A. NAI			B. Is the name listed in Item VIII-A also the owner?
8 DEUBCIN CO	-		YES NO ss (area code & no.)
C. STATUS OF OPERATOR (Enter the appropriate letter into F = FEDERAL M = PUBLIC (other than federal or state) S = STATE O = OTHER (specify) P = PRIVATE	O (specify) CORPOR A 170	3 212	272 6060
E, STREET OR P.O. BOX			
F. CITY OR TOWN B NORT HBROOK		ZIP CODE IX, INDIAN LANI	ted on Indian lands?
X. EXISTING ENVIRONMENTAL PERMITS	40 41 43 47	- \$t	
A. NPDES (Discharges to Surface Water) D. PSD (Air D. P	Emissions from Proposed Source	30	
9 U 9 U	E, ОТИЕЯ (specify)	(specify)	
C. RCHA (Hazardous Wastes) C. RCHA (Hazardous Wastes) C. T. I. T. L. D. 005 1 80 195 9 9	E. OTHER (specify)	(specify)	
XI. MAP Attach to this application a topographic map of the area ext	rending to at least one mile	beyond property bounderies	. The map must show
the outline of the facility, the location of each of its existing treatment, storage, or disposal facilities, and each well when water bodies in the map area. See instructions for precise required.	re it injects fluids undergro	d discharge structures, each o bund. Include all springs, riv	of its hazardous waste ers and other surface
MANUFACTURING =	MACHINING O	OPERATIONS	To
PRODUCE ROTATING 4	INIONS.	194 (1942) 194 (1942)	
I certify under penalty of law that I have personally examinattachments and that, based on my inquiry of those personal application, I believe that the information is true, accurate	sons immediately responsib	le for obtaining the informa	ation contained in the
false information, including the possibility of fine and impri	sonment. 3. SIGNATURE		C. DATE SIGNED
VICE- PRESIDENT COMMENTS FOR OFFICIAL USE ONLY	Karl . L. Bares	usteil	16/8/80



U.S. ENVIRONMENTAL PROTECTION AGENCY HAZARDOUS WASTE PERMIT APPLICATION Consolidated Permits Program

	EP.													
F	I	1	D	0	0	5	1	8	0	1	9	5	T/A	1
-	2							1-0					14	

R	CRA	A			(T)	ris inform	nation	is req	uired	under	Sect	ion 3	008	of	RC	RA.)	1 2			1000			13 14	1 15
				IAL USE ONLY																				
			TIO /ED	(yr., mo., & day)											co	MMENTS					3			
d		73		24 32				, di		1								T.						
II.	FII	RS	ГО	R REVISED APPL	ICATIO	ON		可機是	codes below that best describes each process to be used at the facility. Ten lines are provided for in the space provided, if a process will be used that is not included in the list of codes below, then acce provided on the form (Item III-C). In column A enter the capacity of the process. In column A enter the capacity of the process. In column A enter the capacity of the process. In column A enter the capacity of the process. In column A enter the capacity of the process. In column B (1), enter the code from the list of unit measure codes below that describes the unit of below should be used. In column B (1), enter the code from the list of unit measure codes below that describes the unit of below should be used. In column B (1), enter the code from the list of unit measure codes below that describes the unit of below should be used. In column B (1), enter the code from the list of unit measure codes below that describes the unit of below should be used. In column B (1), enter the code from the list of unit measure codes below that describes the unit of below should be used. In column B (1), enter the code from the list of unit measure codes below that describes the unit of below that descr															
Pla rev EP	ce a ised A I.	n " app	X" i olica Vum	n the appropriate box tion. If this is your fi ber in Item I above.	in A or rst appli	B below ication ar	nd you	alrea	dy kn	ow yo	ur fa	cility	whe	thei PA	th I.D	is is the first a Number, or i	pplicatio f this is a	n you a	re submitt I applicati	ing fo	or you iter yo	r facil our fac	ity o	ra 's.
A.			EX	MO. DAY FOR	See instr Complet	ructions te item b	for defi elow.)	inition	n of "	existin	ig" fi	ATE	(yr.	, me	o., i	& day)	71			FOR	NEW	FACI	LITI	E
8 15 B		5 g	74	6 15 (use 15 75 76 77 78	the box	es to the	left)	11					ON	COI	MM	ENCED		75 76		TION	BEG	ANO	RIS	
	[7	1 1	. FA	CILITY HAS INTER	M STA	TUS				item i	4000	/E)					2. F	ACILIT	YHASA	RCR	A PER	MIT		
Ш	. PI	RO	CES	SES – CODES AN	D DES	IGN CA	PACI	TIES		Sept.	A SA	1877		1										
	desi	erin crib	g co e th	des. If more lines are e process (including it	needed, s design	, enter th capacity	e code / in the	(s) in e spac	the spro	vided o	on th	led, I ne for	f a m (prod I tem	ess 11	will be used t	be used a hat is no	t the fa t includ	cility. Te ed in the l	ist of	s are p codes	provide belov	ed for	n
	1.	AM	IT C	NT — Enter the amount of MEASURE — For a	nt. each am of mea	ount enti sure that	ered in are list	colur	nn B(1), ent	ter th	ne cod					easure co							
				00000	PRO- CESS	MEAS	UREF	OR P	ROC	ESS					-			CESS	MEASU	JREF	ORF	ROCE	ESS	
S	tora	ne:		ROCESS	CODE	DE	SIGN	CAPA	CITY			Tros	o the same	md*		ROCESS		CODE	DES	SIGN	CAPA	CITY		
C		TA	_	R (barrel, drum, etc.)	S01 S02	GALLO						_		2111.				T01				YOR		
			PIL	E		CUBIC	YARD	SOR	ERS			SUF	RFA	CE	IMI	POUNDMENT		T02	GALLO	IS PE	RDA	YOR		
				MPOUNDMENT	504	GALLO			ERS			INC	INE	RA	то	R		T03	TONSPI	ERH	DUR		IR:	
	ispo		-	WELL	D79	GALLONS PER HOUR OR																		
L	AN	DF	PPL	JCATION POSAL	D80	ACRE-F would co depth of HECTA ACRES	VEET (I	the voice acres oot) C TER	olume e to a DR RES			proc surfa ator	mal esse ace s. I	or less no	oiol ot o our ribe	logical treatme occurring in tan ndments or inc e the processes	nt nks, iner- in	T04				YOR		
				MPOUNDMENT		LITERS	PERI	YAC				ine i	o jo tac	c pi	OU.	men, Hem Hi-	0.)							
10	NUT		T NA	ACHDE	UNIT	URE		INILT	OF M	FACIL	0.5				ME	ASURE						MEA	ASUF	RE
				EASURE	COD		-	-									- I Townson	-		A PL		-	-	
L	ITE	RS		DS	1		T	ONS	PER	HOUR			15 15			. D	HEC.	TARE-	METER				F	
C	UBI	CN	/ET	ERS	(G	ALL	ONS	PER H	OUF	2				E	HEC	TARES		* * *			. Q	
EX	AM	PLE	FC	R COMPLETING ITE	EM III (s	shown in	line nu	ımber	rs X-1	and)	X-2 b	elow	1: 1	A fac	eilit	ty has two stor	rage tank	s, one t	ank can he	old 20	00 gall	ons ar	d the	e
oth	er c	an I	hold	400 gallons. The faci	lity also	has an i	ncinera	itor th	nat ca	n burn	up 1	to 20	gal	ons	pe	r hour.								
C I	2		hey.	DUP	13	14 15	11	1	1	//	/	/ ,	/	1	1	111	11,	11	11	1	/	1	1	1
D	A.	PF	20-	B. PROCESS	DESIG	N CAP	ACIT	Y				D.	A.	PR	0-	B. PRO	CESS	DESIG	N CAPA	CITY				
LINE	(fr	OF om bou	list	1. AMC (spec			0	. UNI F ME SURE (enter	A-	FFICI	AL	INE	C (fre	ESS OD	E ist		1. AMO	UNT		OF S	MEA URE enter	OF	FICI	AL
X-:	15 S		18	600	-		27	28 G	29	H	32		16	Ī	18	19	-		2			29	Ť	32
X-2	T	0	3	20				E								abot .	1724	1031						
1	5	0	1	(20 = 55 G	AL.D.	RUMS)	G			10	7					T	Stoy						
)				PIPAUX	1,0	00						8		0	¥			- (pre)						
3				ή.								9	1	10		- William		W.						
4				and Aliverani	Sout.							10												
	16	*	18	19			27	28	20	-	3.7	101	16	7-1	18	10				140	70	70		79.00

SPACE FOR A'DDITIONAL PROCESS CODES OR FOR DESCRIBING OTHER PROCESSES (code "T04"). FOR EACH PROCESS ENTERED HERE INCLUDE DESI IN CAPACITY.

IV. DESCRIPTION OF HAZARDOUS WASTES

- A. EPA HAZARDOUS WASTE NUMBER Enter the four-digit number from 40 CFR, Subpart D for each listed hazardous waste you will handle. If you handle hazardous wastes which are not listed in 40 CFR, Subpart D, enter the four-digit number(s) from 40 CFR, Subpart C that describes the characteristics and/or the toxic contaminants of those hazardous wastes.
- ESTIMATED ANNUAL QUANTITY For each listed waste entered in column A estimate the quantity of that waste that will be handled on an annual basis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste/s/ that will be handled which possess that characteristic or contaminant.
- C. UNIT OF MEASURE For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate codes are:

ENGLISH UNIT OF MEASURE	CODE	METRIC UNIT OF MEASURE	CODE
POUNDS	P	KILOGRAMS	K
TONS	T	METRIC TONS	M

If facility records use any other unit of measure for quantity, the units of measure must be converted into one of the required units of measure taking into account the appropriate density or specific gravity of the waste.

D. PROCESSES

1. PROCESS CODES:

For listed hazardous waste: For each listed hazardous waste entered in column A select the code(s) from the list of process codes contained in Item III to indicate how the waste will be stored, treated, and/or disposed of at the facility.

For non-listed hazardous wastes: For each characteristic or toxic contaminant entered in column A, select the code(s) from the list of process codes contained in Item III to indicate all the processes that will be used to store, treat, and/or dispose of all the non-listed hazardous wastes that possess that characteristic or toxic contaminant.

Note: Four spaces are provided for entering process codes, If more are needed: (1) Enter the first three as described above; (2) Enter "000" in the extreme right box of Item IV-D(1); and (3) Enter in the space provided on page 4, the line number and the additional code(s).

2. PROCESS DESCRIPTION: If a code is not listed for a process that will be used, describe the process in the space provided on the form.

NOTE: HAZARDOUS WASTES DESCRIBED BY MORE THAN ONE EPA HAZARDOUS WASTE NUMBER - Hazardous wastes that can be described by more than one EPA Hazardous Waste Number shall be described on the form as follows:

1. Select one of the EPA Hazardous Waste Numbers and enter it in column A. On the same line complete columns B,C, and D by estimating the total annual

quantity of the waste and describing all the processes to be used to treat, store, and/or dispose of the waste.

In column A of the next line enter the other EPA Hazardous Waste Number that can be used to describe the waste. In column D(2) on that line enter 'included with above" and make no other entries on that line.

3. Repeat step 2 for each other EPA Hazardous Waste Number that can be used to describe the hazardous waste.

EXAMPLE FOR COMPLETING ITEM IV (shown in line numbers X-1, X-2, X-3, and X-4 below) — A facility will treat and dispose of an estimated 900 pounds per year of chrome shavings from leather tanning and finishing operation. In addition, the facility will treat and dispose of three non—listed wastes. Two wastes are corrosive only and there will be an estimated 200 pounds per year of each waste. The other waste is corrosive and ignitable and there will be an estimated ar of that waste. Treatment will be in an incinerator and disposal will be in a landfill.

			EP/				UNIT										D. PROCESSES		
NO.					B. ESTIMATED ANNUAL QUANTITY OF WASTE	5	OF MEA- SURE (enter code)										2. PROCESS DESCRIPTION (if a code is not entered in D(1))		
ζ-1	K	0	5	4	900		P	T	0	3	D	8	0				CANADA AND SE SUR	100	
C-2	D	0	0	2	400		P	T	0	3	D	8	0						
X-3	D	0	0	1	100		P	T	0	3	D	8	0						
X-4	D	0	0	2								1					included with above	e	

Continued from page 2.

NOTE: Photocopy this page before completing if you have more than 26

Form Approved OMB No. 158-S80004


EPA I.D. NUMBER (enter from page 1)					FOR OFFICIAL USE O				IAL USE	DNLY		
WI	WILD005180195 1			1	11		W		DUP		7/A C D U P	
I	DESCRIPTION OF HAZARDOUS WASTES (continued)											
LINE NO.	A. EPA HAZARD. WASTENO. (enter code) B. ESTIMATED ANNUAL QUANTITY OF WASTE		OF MEA- SURE (enter code)		A- E	1. PROCESS CODES (enter)			5	2. PROCESS DESCRIPTION (if a code is not entered in D(1))		
-	23	0	26	27 - 35	4	36 P		27 - 29	27 - 29	27 - 29	27 - 29	,
2	U	2	26	21,096		1		7.7	11	111	11	
			+					11	1.	11	1 1	
3			_						-	-	-	\
4												
5								1 1	1 1			
6			20									
7			T	-				7 1		1 1	1 1	
8								1 1	1 1		, ,	AFIA PONDE VE DO DA LIFE
9												
10				THE STATE OF THE S					1.1		1	A STATE OF THE STA
11				di a equip qui de unagiror, ascrime chaqua for mona alebarit.						TOTAL SERVICE	1 1	the latter of th
12				mater to a future use of a service					1 1	1 1		SALE FOR A POSSIBLE AND A TOTAL
13				87 48 37				1			1 1	22 62 62
14				man and provide the second							T	TORONO ESTADO DE LA CONTRACTOR DE LA CON
15				unal natural				- 1			1 1	
16		mo		In Jugarity 1					117.40		7.12	THE DIMENSION OF THE PERSON OF
17	18											
18												
19										I. I		A Branch Control of the Province of
20	31			w baja mys ni Leonymia i praktini Pari i proje majda vije majda		181			A SLEED			the forth of the forty of the friends of the forty of the
21					4						1 1	perend a mit or test by affindance or rusticalist.
22				09/3/01		1		Jan	1. S.	9-9	1	KARL-L. P. M.KENSTOCK
23												MSG VASAV OUT STORY
1	1-7			allog the attachment form	100	TO STATE OF						
25												when you was set to you know the got the
26	23	7		27 - 35		36		27 - 29	27 - 29	27 - 29	27 - 29	NAME - C. BURNESHOOK
EPA F	orm	35						1	1			CONTINUE ON REVERSE

EPA Form 3510-3 (6-80)

PAGE 4 OF

CONTINUE ON PAGE 5

0861 80 TJO



PHOTOS TAKEN FROM THESE LOCATIONS

87049 39"

LONGITUDE

APROX: (LATITUDE 42002'02"

SCALE I" = 100'0" APROX

A PROX. LOCATION OF STORED MATERIALS



Illinois Environmental Protection Agency · P. O. Box 19276, Springfield, IL 62794-9276

217/782-6762

Refer to: 0312075001 -- Cook County

Northbrook/Deublin Co.

Closure Plan Approved: June 22, 1988 Log #C-402

ILDCOST 601 95 RCRA-Closure

February 1, 1989

Deublin Co. Attn: Richard Shipway 1919 Stanley St., P.O. Box 2157 Northbrook, Illinois 60065

Dear Nr. Shipway:

The subject bazardous waste management facility was inspected by a representative of this Agency on January 20, 1989. The inspection revealed that the closure activity was completed in accordance with the approved closure plan dated June 22, 1988.

Certification that the container (SOI) storage areas A and B had been closed in accordance with the approved closure plan by the owner/operator, Deublin Company, and an independent registered professional engineer, Bakulesh H. Khara, P.E., of Illinois was received at this Agency January 10, 1989.

The Agency has determined that the closure of the container (SGI) storage units A and B has apparently met the requirements of Interim Status Standards. 35 Ill. Admin. Code. Part 725 (40 CFR. Part 265).

This facility must continue to meet the requirements of 35 III. Adm. Code. Part 722 (40 CFR, Part 262) -- Standards Applicable to Generators of Hazardous Waste and 35 111. Adm. Code, Part 723 (40 CFR, Part 263) -- Standards Applicable to Transporters of Hazardous Waste and is no Tanger subject to 35 111. Adm. Code. Part 725 Subpart H (40 CFR, Part 265 Subpart H) -- Financial requirements.



Page 2

If you have any questions, please contact Eugene W. Dingledine at 217/782-5504.

Yery truly yours,

Lawrence W. Eastep, P.E., Menager

Permit Section

Division of Land Pollution Control

LNE: END: bjh/0338k/11,12

cc: Naywood Region USEPA Region V, Mary Murphy USEPA Region V, Art Kawatachi Bakulesh M. Khara, P.E. Division File Andy Vollmer Compliance Section

0 9 AUG 1988

Mr. Richard Shipway Deublin Company 1919 Stanley Street Northbrook, Illinois 60062

> Re: Deublin Company ILD 005 180 195

Dear Mr. Shipway:

The United States Environmental Protection Agency has reviewed the information which you submitted to our office on May 4, 1988, in reference to the above mentioned facility. In addition, the Illinois Environmental Protection Agency has informed us that the restricted waste has been removed off-site. Therefore, based on our review of your documents and the removal of the containers, it has been determined that you have adequately addressed the land disposal restrictions deficiencies outlined in our April 5, 1988, Notice of Violation.


If you have any questions regarding this matter, please contact Zetta L. Thomas of my staff at (312) 886-4581.

Sincerely yours,

Paul E. Dimock, Chief IL/MI/WI Enforcement Program Section

cc: Harry Chappel, IEPA Glen Savage, IEPA Angela Tin, IEPA

DISK 3



U. S. EPA, REGION V SWB - PMS




217/782-6762

Refer to: 0312075001 -- Cook County

RCRA General

June 22, 1988

U.S. EPA, REGION V. Northbrook/Deublin Company woising was assement Division to action of the property of the prop



Karl E. Bremer, Chief Technical Program Section U.S. Environmental Protection Agency Region V 230 South Dearborn Chicago, Illinois 60604

Dear Mr. Bremer:

Enclosed you will find the following:

The Initial Screening for Environmental Significance form for the above referenced facility.

The following form(s) were not on file at the IEPA for this facility:

- Notification of Hazardous Waste Site (EPA Form 8900-1).
- Preliminary Assessment (EPA Form 2070-12).

The Certification Regarding Potential Releases from Solid Waste Management Units has been previously sent.

Based upon a review of the information available on the above referenced facility, the Agency has determined that this facility is not environmentally significant and that a Facility Management Plan should not be prepared. Please let us know if you do not agree with this determination.



Page 2

If you have any questions regarding this initial screening, please contact Eugene W. Dingledine of my staff at 217/782-5504.

Very truly yours,

Kawrence W. Eastep, P.E., Manager

Permit Section

Division of Land Pollution Control

LWE: EWD: syg: 1746j,21-22

Enclosure

cc: Division File

USEPA Region V -- Mary Murphy

FOS Northern Region



Illinois Environmental Protection Agency 2200 Churchill Road, Springfield, IL 62706

217/782-6761

Sefer to:

0312075001 - Cost County

Deublin Co. 11,0005180195 RCRA - Permits

Attn: Environmental Coordinator

or Plant Ranager

Day 6, 1988

Cemblin Co. 1919 Stanley St. Herthbrook, IL 60062

Dear Sir:

According to Agency files, your facility currently manages hazardous waste in containers and/or tanks subject to the requirements of 35 IAC 700-725. 35 IAC 703.167(f) states that interim status for any hazardous waste storage or treatment facility will be terminated Hovember 8, 1992, unless the facility submits Part B of the RCRA permit application for these units to this Agency by Bovember 8, 1988. This letter is written to (1) make you aware of this requirement and (2) describe the actions which must be taken in response to this requirement.

According to 35 IAC 703.767(f), if an existing facility desires to (1) store hazardous waste on-site for greater than minety (90) days, (2) treat hazardous waste, or (3) store hazardous waste as a commercial facility after Hevember 8, 1992, it must submit Part B of the BCRA permit application to this Agency by Movember 8, 1988. The information which must be contained in this application is described in 35 LAC 703, Subpart D. The enclosed document, entitled "RCRA Permit Suidance" provides more detail regarding the necessary contents of the application and also identifies several guidance documents which will be useful in developing the application. Also included in this document is the form which must be used when submitting the application.

If a facility does not desire to continue storing and/or treating hazardous waste after Hovember 8, 1992, it must close the storage and/or treatment unit(s) present at the facility prior to this date. Clesure, in this instance, basically means that all contamination must be removed from the unit(s) and if secessary, from the area surrounding these units. The requirements which must be met in closing these units are contained in 35 IAC 725, Subpart 6. For you convenience, guidance for the development of a closure plan is contained in the enclosed document entitled "Instructions for the Preparation of Closure Plans for Interin Status RCRA Hazardous Haste Facilities." PLEASE BUTE THAT A CLOSURE PLAN DOES NOT HEED TO BE SUBMITTED AT THIS TIME. IT MUST HOWEVER, BE SUBMITTED TO THE AGENCY NO LATER THAN MAY S. 1992.



Page 2

In some instances, there may be several interim status hazardous waste menagement units at a facility. The facility may desire to pursue a final RCRA permit for a portion of these units and close the rest of them. Because of the uncertainty associated with this option, all interip status units at a facility must be included in Part B of the RCRA permit application, unless a closure plan for the units being closed is submitted with the Part B. If a closure plan is submitted with the Part B, the application need only address those units which will remain in operation.

The only alternatives available for hazardous maste treatment and storage facilities to meet the requirements of 35 IAC 703.157(f) are (1) submit Part B of the RURA permit application by Hovember 8, 1988 or (2) close by November 8, 1992. However, some facilities may have previously filed Part A of the RCRA permit application in error and now feel that the hazardous waste management activities carried out at the facility do not require a RCRA permit (i.e. the Part A was filed for protective measures). If this is the case, the Agency requests that information supporting this position be submitted no later than Royauber 8, 1988. The Agency can then review the information submitted and correct its records accordingly. The information which must be submitted to make this demonstration is contained in the enclosed document entitled "Facility Part A Withdrawe Request Form."

Finally, some facilities may have closed or are currently closing in accordance with an IEPA approved closure plan. (Please bear in wind this letter is going out to over 200 facilities; some closed facilities may inadvertently receive this letter.) In this instance, the Agency requests that a copy of (1) the closure plan approval letter and (2) the letter from the Agency accepting the certifications of the owner/operator and the rgistered professional engineer that closure was carried out in accordance with the approved closure plan (if closure has been completed) be submitted by Hovember 8, 1908. The Agency will again be able to review this information and correct its records accordingly.

Because of the large number of facilities subject to the requirements of 35 IAC 703.167(f), the Agency requests that all facilities receiving this letter complete the enclosed form entitled "RCDA Permit Information Form." The form has been developed such that it can be used by a facility falling into any of the five categories described above (pursuing a final permit, planning to close, pursuing a permit for only a portion of the interim status units and closing the other units, protective filers, closed in accordance with an IEPA approved closure plan). This form must be submitted to the Agency no later than Hovember 8, 1988, along with all required attachments. Failure to do so may subject a facility to enforcement under State and/or Federal regulations and possible monetary penalties up to \$25,000 per day of noncompliance.



Page 3

The RCRA Permit Information Form and all required attachments must be submitted in triplicate (original and two (2) copies) to the following address:

Permit Section, RCDA Unit Division of Land Polletion Control Illinois Environmental Protection Agency 2200 Churchill Road P.C. Box 19276 Springfield, IL 62794-9276

If you have any questions regarding this letter, please contact lie Hoore at 217/702-9075.

Very truly yours,

Lawrence W. Eastep, P.E., Manager Permit Section Division of Land Pollution Control

LHE: JRF: mail / 1203J / 1204J /

Enclusures.

cc: Division File Compliance Raywood Region USPEA Penion "

May 4, 1988

Mr. Paul E. Dimock, Chief IL/MI/WI Enforcement Programs Section U. S. Environmental Protection Agency 230 South Dearborn Street Chicago, IL 60604

Subject: Your letter dated April 5, 1988

Dear Mr. Dimock:

Before I address the violations in the above subject letter I would like to bring you up to date as to what occurred before and after the December 18, 1987 inspection by the Illinois E.P.A.

Prior to this inspection, when it came to hazardous waste, Deublin Company considered itself to be a generator with reduced requirements. We learned, however, that when we filed for waste generation in 1980, we also filed for a Part (A) Permit by mistake, which classified us as a TSDF facility at the same time. When Mr. Finley inspected us in December 1987, he stated that Deublin Company was still classified as a TSDF storage facility even though it seemed that we were operating as a generator with reduced requirements.

Since the inspection, a great deal of correspondence has taken place between ourselves and IEPA. I currently have a plan of closure submitted for their review, which I am told is the only way this classification can be resolved. I have been dealing with Ms. Angela Aye Tin of IEPA, Springfield, Illinois.

I would now like to address each of your questions to the best of my ability.

1. Section 268.7(A) (1); Enclosed are copies of Land All Band notices for all F001 waste shipped from Deublin Company in this time period. Our waste hauler has been Safety Kleen for all amounts. I now realize I must keep copies of Land Bands with the Manifest. Mr. Paul Dimock U. S. EPA

Section 265.13

- 2 -

May 4, 1988

At the time of inspection I did not have copies of the waste analysis in my possession. I am enclosing copies of F001 waste analysis which was performed by Safety Kleen. reading Section 265.13, this seems to be describing a TSDF

facility. If IEPA accepts that we are a generator with reduced requirements, I do not believe the entire regulation would apply.

3. Section 265.70

Again, if IEPA accepts our classification as a generator with reduced requirements, I do not believe this section would apply.

In closing, I would like to say that we generate two types of F Solvent waste here, the analysis of which is enclosed. We do not store or process any waste here. We have a licensed waste hauler, currently Safety Kleen Corp., pick up all waste and process it within their organization. This is a service that we have contracted them to perform for Deublin Company. We are, to the best of my knowledge, operating as a generator with reduced requirements.

If you have any questions at all concerning the above, please feel free to call me at (312) 272-6060 between 8:00 A.M. and 4:30 P.M. Monday through Friday.

Sincerely,

Richard Shipway


Sulard Showay

Plant Manager

RTS:md

SENDER: Complete items 1 and 2 when additional and 4. Put your address in the "RETURN TO" Space on the recard from being returned to you. The return receipt fe delivered to and the date of delivery. For additional fees 1. A Show to whom delivered, date, and addressee's	and allure to do this will
PS Form 3811, Mar. 1987 * U.S.G.P.O. 1987-178-268	DOMESTIC RETURN RECEIPT

	P 250 801 2E RECEIPT FOR CERTIFIE NO INSURANCE COVERAGE PRO NOT FOR INTERNATIONAL M.	ED MAIL	
134	(See Reverse) Mr. Richard Shinwa		
k U.S.G.P.O. 1965-460-784	Mr. Richard Shipwa 1919 Stanley Stree		
.0.	P.O., State and ZIP Code	0062	
7.0.0.	Postage	\$.65	
×	Certified Fee	85	
	Special Delivery Fee		60
	Restricted Delivery Fee	8	
7	Return Receipt showing to whom and Date Delivered	90	
000	Return Receipt showing to whom. Date, and Address of Delivery	1 3	
, ,	TOTAL Postage and Fees	\$ 2.40	60
rollii sooo, salle 1903	Postmark or Date)604



OFFICIAL BUSINESS

Print your name, address, and ZIP Code in the space below.

Complete items 1, 2, 3, and 4 on the reverse.

Attach to front of article if space permits, otherwise affix to back of article.

Endorse article "Return Receipt Requested" adjacent to number.



PENALTY FOR PRIVATE USE, \$300

RETURN TO

Print Sender's name, address, and ZIP Code in the space below.

Zetta Thomas

(5HS-12)

U.S. Environmental Protection Agency

230 S. Dearborn, Chicago, IL 60604 05 APR 1988 CERTIFIED MAIL RETURN RECEIPT REQUESTED

Mr. Richard Shipway Deublin Company 1919 Stanley Street Northbrook, Illinois 60062

> Re: Notice of Violation Deublin Company ILD 005 180 195

Dear Mr. Shipway:

On December 18, 1987, the Illinois Environmental Protection Agency (IEPA), representing the U.S. Environmental Protection Agency, conducted a Resource Conservation and Recovery Act (RCRA) inspection of the above-referenced facility. The purpose of the inspection was to determine the facility's compliance with the applicable hazardous waste management requirements of RCRA, including the Federal land disposal restrictions on FOO1-FOO5 spent solvents. The land disposal restrictions became effective on November 8, 1986, (40 CFR Part 268, and revisions to 40 CFR Parts 260-265 and 270-271).

With respect to the land disposal restrictions section of the inspection, your facility was found to be in violation of the following:

- 1. Failure to provide a separate written notice attached to the manifest for each shipment of F-solvent wastes with the U.S. EPA hazardous waste numbers, the applicable treatment standards, manifest number, and waste analysis data, where available, as required by Section 268.7(a)(1);
- 2. Failure to revise the waste analysis plan to include 40 CFR Part 268 requirements in accordance with Section 265.13; and
- 3. Failure to maintain a complete operating record to include 40 CFR Part 268 requirements in accordance with Section 265.73.

A copy of the inspection report is enclosed for your records. Please submit to this office, within thirty (30) days of receipt of this Notice of Violation, documentation demonstrating that the above-cited violations have been corrected and indicating what measures have been initiated to assure future compliance. Failure to correct the violations may subject the facility to further Federal enforcement action.

If you have any questions regarding this correspondence, please contact Ms. Zetta Thomas of my staff at (312) 886-4581.

Sincerely yours,

Paul E. Dimock, Chief IL/MI/WI Enforcement Programs Section

Enclosure

cc: Harry Chappel, IEPA Glenn Savage, IEPA

5HS-12:ZTHOMAS:3/15/88:ea

DISK #3 DOCUMENT 15

			CONCURRENC	ES	4 region of	HISB T SEED T
MBOL		2/11	010			
RNAME	8,9	10/17/80	1.0/			
ATE	2/17/8	2	 3/23/88		-	



Environmental Protection Agency

1701 S. First Street Maywood, IL. 60153

TSD DELETED GIVEN SM Q CODE 2 3.17-82 MAY

copy to PA copy to notif oris to B Stone

312/345-9780

Reter to: General - Cook County - Northbrook/Deublin Company ILD005180195 9 75DPA 3-17-82 mGP

March 9, 1982

Mr. Jack Falls
Deublin Company
1919 Stanley Street
Northbrook, Illinois 60062

Dear Mr. Falls:

On January 26, 1982, representatives of the Illinois Environmental Protection Agency inspected your facility. This inspection was conducted by the Illinois Environmental Protection Agency under a Cooperative Arrangement with, and authorization of, the United States Environmental Protection Agency (USEPA). The purpose of this inspection was to determine your facility's compliance status with the Resource Conservation and Recovery Act of 1976, P.L. 94-580, as amended.

The inspectors found that you are a small quantity generator.
Therefore, if you comply with the requirements of 40 CFR 261.5 you will be exempt from the other regulations under Parts 262 through 265, Parts 122 through 124 and the notification requirements of Section 3010 of RCRA. Should your status change in the future, please be advised that you would have to comply with Part 262 Standards Applicable to Generators of Hazardous Waste published in the Federal Register, Vol. 45, No. 98, on May 19, 1980, as amended.

Please contirm in a letter to us, within 15 days after receipt of this letter, whether you qualify under the special requirements for hazardous waste generated by small quantity generators under the provision of 40 CFR 261.5. Please send such documentation to Mr. Kenneth P. Bechely at the above address.

3 - 19-82

In addition, since your facility will not store hazardous waste, as indicated on your Part A Application, we recommend that you submit a letter to USEPA Region V, RCRA Activities, P.O. Box 7861, Chicago, Illinois 60680, requesting that your EPA Form 3510 Application for Hazardous Waste Permit (Part A) be withdrawn. Copies of this letter should also be sent to USEPA, Enforcement Division, Attention: Water and Hazardous Materials Compliance Section, 230 So. Dearborn Street, Chicago, Illinois 60604, and to the Illinois EPA, at the above address.

Sincerely,

7- must P. Bush

Kenneth P. Bechely, Northern Region Manager Field Operations Section Division of Land/Noise Pollution Control

KPB: GJS: prb

Enclosure: Inspection Report

cc: Division File Northern Region

U.S. E.P.A. - Region V



ILLINOIS ENVIRONMENTAL PROTECTION AGENCY

MEMORANDUM

10:	DATE:
FROM:	Information only
SUBJECT:	Response requested
IL 500518019	5
- Devalue Commence manufactures of	
I was an Assertant The sale and Amilian	
The North Agency Agency and the Street Agenc	
And the second of the second o	
Madella Baldia Para Robane	
A A STONE A A COMPANY OF THE COMPANY	
	44.4 .4 .4.
The second secon	
And I from the Property of the same of the	
	Anning them and the second

RCRA INSPECTION REPORT - INTERIM STATUS STANDARDS TREATMENT, STORAGE, AND DISPOSAL FACILITIES Form A - General Facility Standards

I. General Information:

(A)	Facility	Name: <u>Deublin</u>	Company	
(ċ)	City: _	NOTHBROOK	(D) State:	(E) Zip Code: <mark>∕⊘⊘62</mark>
(F)	Phone:	(317) 272-6060	(G) County:	Cook
(H)	Operator		SAME AS ABO	»v
				(L) Zip Code
(M)	Phone:		(N) County:	
(0)	Owner:		JAME 25 AB	·ove
(P)	Street:			
(Q)	.City: _		(R) State:	(S) Zip Code:
(V)	Date of	Inspection: 1-26-8	(W) Time of Inspec	ction (From) <u>950a</u> (To) <u>[140</u> a
(X)	Weather	Conditions:	1°F Clear	

Rev. 3-6-81/J.B.

(Y) Person(s) Interviewed	Title	Telephone
DAUE May	Plant Mayn Machine Shop Supt	(312) 272-6060 (312) 272-6060
(Z) Inspection Participants <u>Clenn Sternard</u>	Agency/Title IEPA /EPS	Telephone (৪০১) ৪੫૬-৭৮৪১
(AA) Preparer Information		
Name Glenn Sternard	Agency/Title <u>I ERA / EPS</u>	Telephone <u>(312) 345-9780</u>
	II. SITE ACTIVITY:	•
Complete sections I throfacilities. Complete the to the site activities i	ough VII for all treatment, storage, a he forms (in parenthesis) in section V identified below:	nd/or disposal III corresponding
A. Storage and/or Treatme 1. Containers (I) 2. Tanks (J) 3. Surface Impoundmen	(O and P)	or Thermal Treatment
3. Surface Impoundmen 4. Waste Piles (L)B. Land Treatment (M)	그는 사람들이 가는 생각이 되는 것이 되었다. 그는 그들은 것이 되었다면 하는 것이 되었다면 하는데 되었다면 하는데 되었다.	al, and Biological
C. Landfills (N)		
Note: If facility is also a a land X of this form a	generator or transporter of hazardous as appropriate.	waste complete sections

Use this section to briefly describe site activities observed at the time of the inspection. Note any possible violations of Interim Status Standards.

Deubin Company Manufactures Rotating unions of Several types. These unions may accommodate a range of materials, viscosities, rotating speeds, temp & pressures depending on application. The facility machines the raw Metal dastings or torgings to Precision tolerences. The hazardous waste generated is spent III. trichlorosthylen. (Dow Chlorothens). Deublin notified as a generator and Storage facility under RCRA. Information obtained during the inspection revealed that the company notified as a storage tacility in the zvent that materials were on site too 390 days. However, the company officiacs stated that hazardous material Is removed within 90 day. It is recommended that Dublin withdraw its Application for storage facility. It was further. determined that, the rate of generation of hazanepous waste would qualify the tacility for the small-quantity generator status, and the company should delist from the generator program also.

NOTICE OF LAND DISPOSAL RESTRICTION OF WASTE

)	SAFTY KLEEN CORP	EPA ID No.	ILD 980613913	
vesignated Facility:	663 e. 138TH ST			·. ·
	•	•		•
•	DOLTON IL 60419			•
vaste deter the generat	est number <u>IL1918747</u> mined to be restricted under 4 or is hereby providing notice tandards (from Table CCWE of 4	$\overline{0}$ CFR Part 268. In that the waste is re	stricted and the appro	R 268.7
Consti	tuent	Treatment Sta	ndard	
1,1,2-T	RICHLORO-1,2,2-TRIFLUOROETHANE	.960	ppm Use rever	se side
			ppm for addit	fona l
			 ppm constitue	nts
The constit	uent compositions based upon (\ attached data on		
ine constru	dent compositions based upon (, accached data of	(A) knowledge of the	e waste
	TABLE COWE - CO	NETHUBIT IN WASTE EXTRACT		
·		Concent	idon (in mg/l) indonia All other	
	F001-P005 spent solvents		ring	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			사람들이 많은 사람들이 가는 사람들이 모든 그들은 그런 모든 사람들이 되었다.	
	tione:	0.		
Car	bon deutide bon terrachionde		4.01 6	
Cre	probenzene pole (and cresylic acid)		\$	
1.2	dichlorobenzene		25 6	
Eth	d benzane		5 6 .053	
	yl ether - Salah		.75 5.0	
	Nand ::::::::::::::::::::::::::::::::::::		5 75 0 94	
	hytene chloride (from the pharmecoulical Industry) hyt ethyt listone			
Med	nyi leobisyi ketone obenzene	0.0	6 0.33	- 1 V
Pyri	200	1.	2 0.33	
Tak	rechloroethylene	1.1	그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그	
	1 - Trichloroethene 2 - Trichloro - 1,2,2 tifluroethene			
	hioroetryleine hiorofluoromethene		0.001	
	Mg 20000,		and the control of th	
		EP/	10. "一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个	
Generator i		ID#		
enerator i	representative signature	chard should		
Name & Tit	le of representative <i>SICH</i>	MAD SHIDWAY	PLANT MAN	ASKA

NOTICE OF LAND DISPOSAL RESTRICTION OF WASTE

То
Designated
Facility:

SAFETY KLEEN ENVIROUSTEM EPA ID NO. ILD 980613913 633 £ 1385T

POLTON IL 60419

Under manifest number /446695 // (a) the generator noted below is shipping to you a waste determined to be restricted under 40 CFR Part 268. In accordance with 40 CFR 268., the generator is hereby providing notice that the waste is restricted and the appropriate treatment standards (from Table CCWE of 40 CFR 268.41) are as follows:

Constituent		Treatment Standard	
I.I. TRICHWROSTHANE		.96 ppm	Use reverse side
		ppm	for additional
	,	ppm	constituents
The constituent compositions based upon ()	attached data or () know	wledge of the waste.

TABLE COWE - CONSTITUENT IN WASTE EXTRAC

F001-F005 spent épivents	Concentration (in mg/l) Wastewaters containing spent solvents	All other spent solvent wastes
Acetone -Butvi alcohol	0.05	0.50
	5.0	5.0
arbon disuffide arbon tetrachtoride	1.05	4.81
	05	.96
hiorobenzéne resinté (and crassitio exidi	.15	.05
resols (and cresylic acid)	2.82	.75
yclohexanone ,2 - dichloroberizene	125	.75
	.68	.125
Inyl acetate thyl benzene	.05	.75
hy ether	.05	.053
obutano	.05	.75
ethanol	5.0	5.0
lethylene chloride	.25	.75
ethylene chloride (from the pharmaceutical industry)	20	.96
lethyl ethyl ketone	12.7	.96
fethyl isobutyl ketone	0.05	0.75
irobenzene	0.05	0.33
yidne	0.65	0.125
etrachloroethylene	1.12	0.33
Oliene	0.079	0.05
.1.1 - Trichloroethane	1.12	0.33
2.2 - Trichloro - 1.2.2 trifluroethane	1.05	0.41
ichloroethylene	1.05	0.96
richlorofluoromethene	0.062	0.091
ylene	0.05	0.96
,	0.05	0.15

Generator name DEUBUN Co.	EPA ID#: 1LD005180195
Generator representative signature	lucker Ifhalia.
Name & Title of representative (print or type)	CYPED SHIPURY PHAT MARKE
(print or type)	and the first of the second

FLUID RECOVERY SERVICE

Lab Number: 205/1/1 SK Sample No.: 13		stomer	No:		-					
Ship To Address: 1919 Stanley	Customer Name: Bill To Address:		· · · · · · · · · · · · · · · · · · ·	<u> </u>	: .					
City/State/Zip: Northbrook 11 60062	-		·							
Customer Phone: (3/2) 272-6060	Date of let Pick Up:				· · · · · · · · · · · · · · · · · ·					
Customer Contact 1sts Rick Shipway	Pick Up Quantity:	The second	1	<u> </u>	· · · · · · · · · · · · · · · · · · ·					
Customer Contact 2nd:	P. O. Number:									
U.S. EPA ID Number: <u>ILD005180195</u>	Service Interval:	4 we	eks		**************************************					
State EPA ID Number: 03/4670001	Scheduled Pricing:	\$ 150								
03/2075001	Nonscheduled Pricing:	125	\circ	1 -						
					\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.					
. Transporter 1 Company Name 6.	US EPA ID Number	C.Illino	is Trancorter's	ID OI	[1] 1 12 [3					
SAFETY-KLEEN CORP.	ILD051060408	D.(312) 766-6614 Transporter's Phon								
. Transporter 2 Company Name 8.	US EPA ID Number	E.Ilinois Transporter's ID								
D. Designated Facility Name and Site Address 10.	US EPA ID Number	Gillino	lity's							
SAFETY-KLEEN ENVIROSYSTEMS CORP. 633 E. 138TH STREET		ID 1 0 13 11 10 1 6 1 9 10 10 10 1 HFacility's Phone								
DOLTON, IL 60419	ILD980613913		(312) 849-4850							
11. US DOT Description (Including Proper Shipping Name, Hazard		ntainers Type	13. Total Quantity	14. Unit	Ł Waste No.					
WALREDOWN WASTE LUDWID, H.O. S., ORM			Quarinty	1	EPA HW Namber					
(TEICHLOROTE FLUOROCTHANE					Authorization Number					
(EPA, TOXICITY, FOOL)			1 1 1 1		0000036					

Ł

100USTRIAL SQLVENTS 07/16/87 07/16/87 07/16/87 07/16/87 07/16/87

---- SPECIAL PROCESSING INSTRUCTIONS --DATE SUBMITTED 07/06/87 DATE ANALYZED 07/06/87 CHEMIST - GLL 07/06/87 S/C - 19 # FAST OR SPG # GOF----> 1.4

* FAST POINT ------> NA

* VISCOSITY------> NA

* VISCOSITY------> NA

* VISCOSITY------> NA

* VISCOSITY------> NA

* VISCOSITY-----> NA

* VISCOSITY-----> NA

* VISCOSITY-----> NA

* PEDSTORMAN FOR NA

* PEDS LAB NUMBER----> 705171 SK-SAMPLE-NO. ----> (3401 SK-CUST-NO----> FREON RECOVERY FRS.CAT.III.
UNH OT-16-87

* DATE REVIEWED OT/16/87

* REVIEWED BY LWG

* REVIEWED BY LWG

* ANALYSIS TYPE 0569 DN 07/06/87 1113 CUST MAME ----- DEUBLIN CO.
ADDRESS ------ 1819 STANLEY
CITY/STATE/ZIP-- NORTHBROOM
CUST CHARLEY STANLEY
CUST CHARLEY STANLEY
USERN IO MO---> 316/Z18-6606
CUST CONTACT ---> 316/Z18-6606
CUST CONTACT ---> 116/C05180195
STATE EN ADO---> 10005180195
STATE EN ADO---> 10005180195
GREEN SHEET 7--> YES
GREEN SHEET 7--> YES
GREEN SHEET 7--> YES
GREEN SHEET 7--> YES
GREEN SHEET STANLES SAMPLE
SAMPLE STEE--->
GRUEN SAMPLED--->
GREEN SHEET SAMPLE
COMMENTS ----> P.O. #61073/LRS SAMPLE
COMMENTS ---->
SUBMITTED BY---> GRUCE VAN DEN BROUCKE • 0 • HETALS DATA

ar as , — , — s		. Por refere	: 10 - 10 <u>-</u>	- 15					anai,	
	· · · · ·							sed.	insi,	
taga yana bili digiri		·					p. Papa	À		÷,
	LANANA	dra			Mik			A har		10
ing destricted by their	ees Seegeleese			. Alia			j Add	part :	Napal	
The second property of the property						5				
A Company of the American	,								restiye.	
granical affinish						194	(Mari	147		작.
egyelte kirik degli elgelte k		Parketer Parketer								117
Applicable Consideral Minuse	•	1,0			M.		٠.	٠.,	1	

The second secon	ka ka ka ana daka ka ka ka ka ka ana ka ana ka
그는 사람들은 사람들은 얼굴은 교육을 보고 있다. 그는 그들은 등록을 통한 사람들은 모양하는 것이다. 한국 등은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들	
그는 그는 그를 보고 있는 그는 사람들은 가득한 다른 전쟁하다면 하는 그는 사람들이 되었다면 하는 것이 되었다.	그 경기에게 얼마를 받아 보다면 되었다고요? 사람
	of the west values are trained to the state of the second of the second
아이아 아이는 아이들이 아이들이 아이들이 아이들은 사람들은 사람들이 아니는 사람들은 사람들이 되었다. 그는 사람들이 나를 가지 않는 것이 없는 사람들이 없다.	Alteratur, kalingiya ili kamana dibakamini itali mila
	그리 원리 사람들은 얼마나 살았다. 항로 살아 살아 있는 것도 하는
	불명하다 한글을 모르고 보고 하고 말 먹는 것, 하고 있는 하는 그 것은
	그 사람들은 사람들이 얼마를 하는 것이 되었다. 그 사람
and the control of th	
。	
a stella de la companya de la compa	
and the control of the first of the community of the control of th	
그는 그는 그를 보고 살고 있을 때 그 등으로 그는 그들은 사람이 가장하게 하게 하게 하지만 하게 하게 하게 하는 것이 생각이 하는 것이 없다.	
na 1988 seepsi na kalikan malakan katala kan na maran kan mana kali kali kata kali kali wata kata katala kalika	
	경우 보통 살 없는 것은 것은 것은 것은 것은 것은 것은 것은 것은 것이다. 나는 것은
그리는 사람들은 그리고 가는 그는 그를 가는 사람들은 학생들은 그는 그를 가는 것을 하는 것을 하는 것을 하는 것을 하는 것을 하는 것을 하는 것	
그리트를 하지만 하면 함께 보는 그는	스러는 이 사람이 들어 얼마를 만든 것으로 만든 것이다.
· 她就是她她就能够了,"我们是一个人,我们是一个人的,我们就是一个人的人,我们就是一个人的人,我们就是一个人的人的,我们就是一个人的人的人,不是一个人的人 的人	
화물병으로 보면 보면 보는 것이 되었다. 그 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은	됐다. 그리는 그리를 하면 있는 것을 하는 것이 없는 것이 없다.

HAZARDOUS WASTE

FEDERAL LAW PROHIBITS IMPROPER DISPOSAL

IF FOUND, CONTACT THE NEAREST POLICE, OR PUBLIC SAFETY AUTHORITY, OR THE U.S. ENVIRONMENTAL PROTECTION AGENCY

PROPER D.O.T. HAZAR BOUS WASTE 2/80/2 NOS, FOO!
SHIPPING NAME AND - F THICH HOROZAV LAKO AD UN OF NA 9APS
FER TOURS ETHANE

GENERATOR INFORMATION:

NAME DEUBLIN CO.

ADDRESS 1919 STANLEY

CITY NORTHBROOK

EPA ID NO. <u>/L 2005 /80 /95</u> EPA WASTE NO._

ACCUMULATION START DATE MANIFEST DOCUMENT NO.

HANDLE WITH CARE!

CONTAINS HAZARDOUS OR TOXIC WASTES

STYLE WM-5

FLUID RECOVERY

Lab Number: 105/72 Customer Name: Deublirt (Ship To Address: 1919 St. City/State/Zip: Northbrox Customer Phone: (3/2) 273 Customer Contact 1st: Rick Customer Contact 2nd: Drive U.S. EPA ID Number: 110 C State EPA ID Number: 03/4	ok ! 11 60062 2-6060 Shioway	102 Customer Name: Bill To Address	SR Cus	tomer	No.		
5. Transporter 1 Company Name	6.	US EPA ID Numbe		I.			<u> </u>
SAFETY-KLEEN CORP.		D051060408			s Tranporter's) 766-6614		11 1 2 3
7. Transporter 2 Company Name	8.	US EPA ID Numbe			s Transporter's		I I I I
9.00				FI	Design of the		nsporter's Phone
9. Designated Facility Name and Site Addi SAFETY-KLEEN ENVIROSYSTEMS CORP. 633 E. 138TH STREET DOLTON, 1L 60419	l u	US EPA ID Numbe .0980613913		and the second second		11101	6,9,0,0,0,6
11. US DOT Description (including Proper	r Shipping Name, Hazard Cl	ess, and ID Number)	12.Cont		13.	114	t
ASTE 1,1,1 TRICHL			No.	Туре	Total Quantity	Unit WUVo	Waste No.
X UN2831, CEPA, TO,		M-A		DM			XXIFIOOII
CUST NAME	TESTS: SPG PS	TOLUÉNE	C C C C C C C C C C C C C C C C C C C				

PRE/SHIP ANALYSIS - C.O.M.P.L.E.T. & D. 40540 - R2063

DECEVED

ON O STEPA REGION VISION

WASTE MANAGENED DIRECTOR

WASTE OF THE DIRECTOR

OFFICE OF

HAZARDOUS WASTE

FEDERAL LAW PROHIBITS IMPROPER DISPOSAL

IF FOUND, CONTACT THE NEAREST POLICE, OR PUBLIC SAFETY AUTHORITY, OR THE U.S. ENVIRONMENTAL PROTECTION AGENCY

PROPER D.O.T. WASTE 1.1. I TAICH LOADETHING:
SHIPPING NAME OF MINE OF THE PROPERTY OF THE PROP

GENERATOR INFORMATION:

NAME DEUSLIN -CO.

ADDRESS 1919 STANLEY

ADDRESS 19/1 9/1/V LC

EPA

ID NO. 242005 180 193

ACCUMULATION START DATE

EPA

WASTE NO...
MANIFEST

DOCUMENT NO

HANDLE WITH CARE!

STYLE WM-

C LABELMASTER, CHICAGO, IL 80846

13400



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 5 77 WEST JACKSON BOULEVARD CHICAGO, IL 60604-3590

REPLY TO THE ATTENTION OF:

HRE-8J

May 12, 1993

Mr. Richard T. Shipway Plant Manager Deublin Company 1919 Stanley Street Northbrook, Illinois 60062

Re:

Visual Site Inspection Deublin Company Northbrook, Illinois ILD 005 180 195

Dear Mr. Shipway:

The U.S. Environmental Protection Agency is enclosing a copy of the final Preliminary Assessment/Visual Site Inspection (PA/VSI) report for the referenced facility. The executive summary and conclusions and recommendations sections have been withheld as Enforcement Confidential.

If you have any questions, please call Francene Harris at (312) 886-2884.

Sincerely yours,

Kevin M. Pierard, Chief

Minnesota/Ohio Technical Enforcement Section

RCRA Enforcement Branch



TES 9

Technical Enforcement Support at Hazardous Waste Sites Zone III Regions 5,6, and 7



PRC Environmental Management, Inc. 233 North Michigan Avenue Suite 1621 Chicago, IL 60601 312-856-8700 Fax 312-938-0118



PRELIMINARY ASSESSMENT/ VISUAL SITE INSPECTION

DEUBLIN COMPANY NORTHBROOK, ILLINOIS ILD 005 180 195

FINAL REPORT

Prepared for

U.S. ENVIRONMENTAL PROTECTION AGENCY Office of Waste Programs Enforcement Washington, DC 20460

Work Assignment No. : C05087

EPA Region :

 Site No.
 :
 ILD 005 180 195

 Date Prepared
 :
 March 12, 1993

 Contract No.
 :
 68-W9-0006

PRC No. : 009-C05087IL8N

Prepared by : PRC Environmental Management, Inc.

Contractor Project Manager : (Terry Quirk)
Shin Ahn

Telephone No. : (312) 856-8700

EPA Work Assignment Manager : Kevin Pierard Telephone No. : (312) 886-4448

TABLE OF CONTENTS


Secti	<u>on</u>																					<u>P</u>	age
EXE	CUTIV	E SUMM	IARY			• • • •					• • •				• • •							. E	S-1
1.0	INTI	RODUCT	TION .	• • • • •					• • •														1
2.0		ILITY DI					医高基基酚						5.3%		1.5				1	19.3			ja ka
	2.1	FACIL	LITY L	OCAT	ΓΙΟΝ			•••															4
	2.2	FACIL	LITY O	PERA	IOITA	NS .			• • •		• • •												4
	2.3	WAST	E GEN	ERAI	ΓΙΟΝ	ANI	D M	ANA	GEN	MEN	1T		•	• •		• •	•			•			6
	2.4	HISTO	DRY OF	DOC	UMI	ENTE	ED R	ELE	ASE	:S .	• • •	• •	•	• • •			• •	•	•				11
	2.5 2.6	KEGU	JLATO	KYH.	1210	RY			• • •	• • •	• • •		• •	•			•		. 1.1	•			11
	2.0	ENVIR	RONM	LNIA	ıL SE	.1111	NG.		• • •		• • •		•	•	•	•	•	•		• •	•		12
		2.6.1	Clima	to																Ņ			
		2.6.2	Flood	Plain	and (Surfa	ca W	oter	• • •	• • •	• • •	•		•	•			•	•	• •	• • •		1000
		2.6.3	Geolo	ov and	tio2 b	c		atei					•		•		•	•		•	• • •	•	13 13
		2.6.4	Groun	id Wat	ter .							•	•	•	• •		•		•	•			13
										A Sh			1136			di g	453	441	314	3.3	43.		
	2.7	RECE	PTORS	• • • •					• • •	• • •	• • •		•		••	•	• •		•	•	• • •	•	14
3.0	SOLI	D WASTI	E MAN	IAGE	MEN	IT UN	NITS	•							•					•			16
4.0	ARE	AS OF C	ONCE	RN					• • •		• • •												22
5.0	CON	CLUSION	NS ANI	D REC	COMI	MEN	DAT	ION	S														23
																				ξŅ.	A. H.		
REFI	ERENC	ES																					26
Attac	<u>hment</u>																						
A	EDA	PRELIM	TATADS	Z A CCT	ecci.	er Nitr	· FOI		1070	• •													
				Mark																			
В	VISU	AL SITE	INSPE	CTIO	N SU	ІММ .	ARY	AN	D PI	TOH	OC	R.	API	HS									
<u></u>	VISIT	AI CITE	INICDE	CTIO	NI ETI	EI D	NOT	TCC .															

LIST OF TABLES

<u>Table</u>		Page
1	SOLID WASTE MANAGEMENT UNITS	7
2	SOLID WASTES	9
3	SWMU SUMMARY	. 25
	LIST OF FIGURES	
Figur		<u>Page</u>
1	FACILITY LOCATION	5
2	FACILITY LAYOUT	0

RELEASES 100 PRINTERS TO THE P

EXECUTIVE SUMMARY



PRC Environmental Management, Inc. (PRC), performed a preliminary assessment and visual site inspection (PA/VSI) to identify and assess the existence and likelihood of releases from solid waste management units (SWMU) and other areas of concern (AOC) at the Deublin Company (Deublin) facility in Northbrook, Cook County, Illinois. This summary highlights the results of the PA/VSI and the potential for releases of hazardous wastes or hazardous constituents from SWMUs and AOCs identified. In addition, a completed U.S. Environmental Protection Agency (EPA) Preliminary Assessment Form (EPA Form 2070-12) is included in Attachment A to assist in prioritizing RCRA facilities for corrective action.

The Deublin facility formerly manufactured rotating unions for a variety of industrial uses. The facility began operations in 1957 and ceased operations on December 7, 1992, when the company moved all its operations to a new building in Waukegan, Illinois. Deublin has been the only occupant of the facility since it was built, and facility operations have been the same since Deublin occupied the facility. The facility employed 130 people in a light- to medium-use industrial area.

The following wastes were generated at the facility: waste still bottoms (D001 and F001), waste coolants (D001), waste oil (D001), waste lapping sludge (D001), and nonhazardous scrap metal. These wastes were ultimately shipped off site for treatment or disposal.

On October 8, 1980, the facility submitted a Part A permit application that identified the facility as a generator and as a treatment, storage, or disposal (TSD) facility that listed container storage (S01) for two areas: Container Storage Areas (CSA) A and B (SWMUs 1 and 2). In April 1988, Deublin submitted a closure plan for CSAs A and B to Illinois Environmental Protection Agency (IEPA) and requested the change of its status from a TSD facility to a small quantity generator of hazardous waste. On June 22, 1988, IEPA approved this closure plan. Roy F. Weston, Inc. (Weston) conducted closure activities for CSAs A and B (SWMUs 1 and 2) on October 15, 1988. Sampling for F001 solvents was conducted of the rinsate from washing of the CSAs and all results were below detection limits. Weston submitted a Closure Certification Statement and a Closure Documentation Report to IEPA on January 9, 1989. On February 1, 1989, IEPA approved the closure of CSAs A and B and changed Deublins status to that of a small-quantity generator of hazardous wastes. Deublin continued to operate as a small quantity generator of hazardous waste until the facility moved to a new location on December 7, 1992.

ENFORCE SENT CONFIDENTIAL

The PA/VSI identified the following six SWMUs at the facility. No AOCs were identified.

Solid Waste Management Units

1. Container Storage Area A

2. Container Storage Area B

3. Container Storage Area C

4. Degreaser and Still

5. Scrap Metal Accumulation Area

6. Coolant Reclamation Unit

RELEASED TOO
RIN #_______
INITIALS_________

Because all facility SWMUs are either RCRA closed or inactive, and because all were located indoors, the potential for release to all environmental media is low.

Receptors of potential releases include Deublin personnel and residents of Northbrook, Illinois. The nearest residence is located within 0.25 mile west of the facility. The nearest schools are located 0.5 mile southwest of the facility and 0.5 mile west of the facility. Facility access is limited to a degree by a chain-link fence and by locked doors and burglar alarms.

An unnamed pond located about 0.25 mile east of the facility is the surface water body nearest the facility. This pond is not used for any known purpose. Lake Michigan is located about 3 miles east of the facility and is the only source of drinking water for the area. Ground water is not used for drinking water in the area, and no wells are located in the area. Surface water runoff is towards the north and enters the storm sewer system.

No sensitive environments are located on site. However, wetland areas greater than 2 acres in size are located within 1 mile northeast of the facility.

PRC recommends no further action for the facility.

1.0 INTRODUCTION

PRC Environmental Management, Inc. (PRC), received Work Assignment No. C05087 from the U.S. Environmental Protection Agency (EPA) under Contract No. 68-W9-0006 (TES 9) to conduct preliminary assessments (PA) and visual site inspections (VSI) of hazardous waste treatment and storage facilities in Region 5.

As part of the EPA Region 5 Environmental Priorities Initiative, the RCRA and CERCLA programs are working together to identify and address RCRA facilities that have a high priority for corrective action using applicable RCRA and CERCLA authorities. The PA/VSI is the first step in the process of prioritizing facilities for corrective action. Through the PA/VSI process, enough information is obtained to characterize a facility's actual or potential releases to the environment from solid waste management units (SWMU) and areas of concern (AOC).

A SWMU is defined as any discernible unit at a RCRA facility in which solid wastes have been placed and from which hazardous constituents might migrate, regardless of whether the unit was intended to manage solid or hazardous waste.

The SWMU definition includes the following:

- RCRA-regulated units, such as container storage areas, tanks, surface impoundments, waste piles, land treatment units, landfills, incinerators, and underground injection wells
- Closed and abandoned units
- Recycling units, wastewater treatment units, and other units that EPA has
 usually exempted from standards applicable to hazardous waste
 management units
- Areas contaminated by routine and systematic releases of wastes or
 hazardous constituents. Such areas might include a wood preservative
 drippage area, a loading or unloading area, or an area where solvent used to
 wash large parts has continually dripped onto soils.

An AOC is defined as any area where a release of hazardous waste or constituents to the environment has occurred or is suspected to have occurred on a nonroutine and nonsystematic basis. This includes any area where a strong possibility exists that such a release might occur in the future.

The purpose of the PA is as follows:

- Identify SWMUs and AOCs at the facility
- Obtain information on the operational history of the facility
- Obtain information on releases from any units at the facility
- Identify data gaps and other informational needs to be filled during the VSI

The PA generally includes review of all relevant documents and files located at state offices and at the EPA Region 5 office in Chicago.

The purpose of the VSI is as follows:

- Identify SWMUs and AOCs not discovered during the PA
- Identify releases not discovered during the PA
- Provide a specific description of the environmental setting
- Provide information on release pathways and the potential for releases to each medium
- Confirm information obtained during the PA regarding operations, SWMUs, AOCs, and releases

The VSI includes interviewing appropriate facility staff; inspecting the entire facility to identify all SWMUs and AOCs; photographing all visible SWMUs; identifying evidence of releases; making a preliminary selection of potential sampling parameters and locations, if needed; and obtaining additional information necessary to complete the PA/VSI report.

This report documents the results of a PA/VSI of the Deublin Company (Deublin) facility (EPA Identification No. ILD 005 180 195) in Northbrook, Cook County, Illinois. The PA was completed on January 18, 1993. PRC gathered and reviewed information from the Illinois Environmental Protection Agency (IEPA), Federal Emergency Management Agency (FEMA), U.S. Department of Agriculture (USDA), U.S. Department of Commerce (USDOC), U.S. Geological Survey (USGS), and from EPA Region 5 RCRA files. The VSI was conducted on February 1, 1993. It included interviews with facility representatives and a walk-through inspection of the facility. PRC identified six SWMUs and no AOCs at the facility.

PRC completed EPA Form 2070-12 using information gathered during the PA/VSI. This form is included in Attachment A. The VSI is summarized and 11 inspection photographs are included in Attachment B. Field notes from the VSI are included in Attachment C.

2.0 FACILITY DESCRIPTION

This section describes the facility's location; past and present operations; waste generating processes and waste management practices; history of documented releases; regulatory history; environmental setting; and receptors.

2.1 FACILITY LOCATION


The Deublin facility is located at 1919 Stanley Street in Northbrook, Cook County, Illinois (latitude 42°07'07" N; longitude 87°49'39" W) (Deublin, 1980b). The facility occupies about 80,000 square feet of land in a light- to medium-use industrial area. The location of the Deublin facility is shown in Figure 1.

Deublin is bordered on the north by the Maurice Company across Stanley Street; on the east by Agrimerica, Inc.; on the south by the Illinois Department of Transportation facility and the MagneCraft Company; and on the west by the Robco Company.

Facility access is partially limited by a chain-link fence that surrounds the parking area on the eastern side of the facility. Access to the rest of the facility is limited by locked doors and burglar alarms.

2.2 FACILITY OPERATIONS

The Deublin facility manufactured rotating unions until December 7, 1992, when company operations were moved to a new plant in Waukegan, Illinois. Rotating unions are machined, stationary mechanical devices that are inserted into hollow-cored rollers such as those used to move hot steel ingots. These unions contain heat-transfer fluids that allow for cooling of the hot products as they move over the rollers. The unions can be made from stainless steel, brass, or aluminum. Processes associated with the manufacture of the unions after metal castings or forgings are received include cutting, milling, grinding, and threading. Before closing, the facility employed 130 people. The facility typically operated with one full 8-hour shift and two partial 8-hour shifts per day, 5 days per week. Solid wastes generated by facility operations and the SWMUs where they are managed are discussed in detail in Section 2.3.



Facility operations took place inside a 35,000-square-foot building. During machining operations, the facility used a vapor Degreaser and Still (SWMU 4) to clean finished parts. Machinery coolant was cleaned and recycled in two coolant recycling tanks in the Coolant Reclamation Unit (SWMU 6). Containerized wastes were managed in Container Storage Areas (CSA) A, B, and C (SWMUs 1, 2, and 3, respectively). CSAs A and B were approved as RCRA closed by IEPA on February 1, 1989 (IEPA, 1989). Scrap metal was stored in the Scrap Metal Accumulation Area (SWMU 5).

The Deublin facility began operations in 1957 and ceased operations on December 7, 1992, when the company moved its operations to a new building located at 2050 Norman Drive West, Waukegan, Illinois, 60085-6747. Deublin has been the only occupant of the facility since it was built, and facility operations have been the same since Deublin occupied the facility. All salvageable equipment has been moved out of the facility, and the entire property is in the process of being sold.

2.3 WASTE GENERATION AND MANAGEMENT

This section describes waste generation and management at the Deublin facility. The facility's SWMUs are identified in Table 1. The facility layout, including the SWMUs, is shown in Figure 2. The facility's waste streams are summarized in Table 2. Waste codes were assigned to each waste by the facility after a waste analysis was performed by Safety-Kleen Corporation and included on their biennial reports to EPA.

Waste still bottoms (D001, F001) were generated from the use of petroleum naphtha; 1,1,1-trichloroethane (TCA); and freon at various times to degrease metal before and after machining. These solvents were used, at various times, in a combination Vapor Degreaser and Still (SWMU 4). As degreaser solvent became contaminated, it was pumped into the attached still for reclamation. Waste still bottoms from the still were drummed and immediately stored in one of the three CSAs (SWMUs 1, 2, and 3). After 1983, these waste still bottoms were stored on site in all three CSAs (SWMUs 1, 2, and 3) for less than 90 days; and after 1989, in CSA C only (SWMU 3). At the time facility operations ceased, only petroleum naphtha was being used for degreasing. Deublin generated about 200 gallons of waste still bottoms every month. All waste still bottoms were transported to Safety-Kleen Corporation in Franklin Park, Illinois, for reclamation.

TABLE 1
SOLID WASTE MANAGEMENT UNITS

SWMU Number	SWMU Name	RCRA Hazardous Waste Management Unit*	Status
1	CSA A	Yes	Inactive; RCRA closed in 1989
2	CSA B	Yes	Inactive; RCRA closed in 1989
3	CSA C	No	Inactive
4	Degreaser and Still	No	Inactive
5	Scrap Metal Accumulation Area	No	Inactive
6	Coolant Reclamation Unit	No	Inactive
Note:			
A	RCRA hazardous waste manag	tement unit is one that curre	ently requires or formerly

A RCRA hazardous waste management unit is one that currently requires or formerly required submittal of a RCRA Part A or Part B permit application.




TABLE 2 SOLID WASTES

Waste/EPA Waste Code	Source	Solid Waste Management Unit 1 2, 3, and 4
Waste still bottoms/D001, F001	Degreaser and Still	
Waste coolants/D001	Production machinery	1, 2, 3, and 6
Waste oil/D001	Production machinery	l, 2, and 3
Waste lapping sludge/D001	Grinding	1, 2, and 3
Scrap metal/NA	Grinding and cutting	40 (4) (4) (4) (4) (4) (4) (4) (4) (4) (4)
Notes:		
 Not applicable (NA) designat 	es nonhazardous wasta	

Not applicable (NA) designates nonhazardous waste.

Waste coolants (D001) were generated from maintenance of facility machinery. As coolant was replaced in the machinery, waste coolant was transferred to the Coolant Reclamation Unit (SWMU 6). This unit consisted of two interconnected, 250-gallon tanks. Waste coolant was added to the first tank, allowed to separate from contaminants, and then piped into the second tank. A mixture of waste coolant and oil was skimmed off the coolant in the first tank and put into a 55-gallon drum. After the coolant was transferred to the second tank, heavier contaminants such as shop dirt and metal fines were scooped out and added to the drum with the waste coolant-oil mixture. Drums of this waste coolant-oil mixture were then immediately transferred to one of the three CSAs (SWMUs 1, 2, and 3). After 1983, this waste coolant-oil mixture was stored on site for less than 90 days. Deublin generated about 100 gallons of waste coolant-oil mixture every month. All waste coolant-oil mixture was transported to Safety-Kleen Corporation in Franklin Park, Illinois, for reclamation.

Waste oil (D001) was generated from the use of cutting oil for routine machine maintenance. This waste oil was collected directly from machines into a 55-gallon drum. Drums of waste oil were immediately transferred to one of three CSAs (SWMUs 1, 2, and 3). After 1983, this waste oil was stored on site for less than 90 days. Deublin generated about 150 gallons of waste oil every month. All waste oil was transported to Safety-Kleen Corporation in Franklin Park, Illinois, for reclamation.

Waste lapping sludge (D001) was generated from grinding operations. Oil would combine with metal fines and shop dirt from the grinding operation to form a viscous, oily sludge called lapping sludge. This lapping sludge was collected at the point of generation into a 55-gallon drum. Drums of the waste lapping sludge were immediately transferred to one of the three CSAs (SWMUs 1, 2, and 3). After 1983, this waste lapping sludge was stored on site for less than 90 days. Deublin generated about 320 gallons of waste lapping sludge every year. All waste lapping sludge was transported to Safety-Kleen Corporation in Franklin Park, Illinois, for reclamation.

The cutting and grinding operation at the facility generated scrap brass, steel, and other metals. These scrap metals were accumulated and stored in 55-gallon drums in the Scrap Metal Accumulation Area (SWMU 5). Deublin generated about 625 cubic yards of scrap metal every year. All scrap metal generated at the facility was transported to Universal Scrap Metal of Chicago, Illinois.

There is no record of waste management practices for the facility prior to 1980, when the facility began RCRA management of their wastes.

2.4 HISTORY OF DOCUMENTED RELEASES

There have been no documented releases of hazardous wastes at the facility.

2.5 REGULATORY HISTORY

On August 26, 1980, the Deublin facility submitted a Notification of Hazardous Waste Activity Form as a generator and treatment, storage, or disposal (TSD) facility (Deublin, 1980a). On October 8, 1980, the facility submitted a Part A permit application. This application listed container storage (S01) of TCA (U226) waste for CSAs A and B (SWMUs 1 and 2) and having a total capacity of 1,000 gallons (Deublin, 1980b).

On January 26, 1982, IEPA inspected the Deublin facility. In a letter sent to the facility, IEPA stated that the inspectors had determined that the facility qualified as a small-quantity generator of hazardous waste. IEPA also recommended that the facility petition EPA for a withdrawal of Deublin's Part A permit application (IEPA, 1982). On May 26, 1983, EPA sent a letter to Deublin stating that it had reviewed the facility's Part A permit application, that the facility might not be required to have a Part A permit, and that the facility might qualify as a small-quantity generator of hazardous waste (EPA, 1983).

On June 8, 1983, Deublin sent a letter to EPA stating that, through an error on the facility's part, it had stored hazardous waste at CSAs A and B (SWMUs 1 and 2) on site for about 14 months and was in the process of disposing of this waste (Deublin, 1983). The facility went on to request that it be allowed to withdraw its Part A permit application and that it be accorded small-quantity generator status. On May 2, 1984, EPA denied Deublin's request for withdrawal of its Part A permit application (EPA, 1984).

On December 18, 1987, IEPA inspected the facility for compliance with RCRA. As a result of the inspection by IEPA, EPA sent a letter to the facility on April 5, 1988, citing the facility for the following: failure to include Land Disposal Restriction (LDR) notifications with manifested shipments of F001 solvent wastes; failure to update the waste analysis plan to include F001 solvent wastes; and failure to maintain a complete operating record as required for a facility

subject to TSD regulations (EPA, 1988a). On May 4, 1988, Deublin responded to EPA in a letter stating that it had addressed the violations (Deublin, 1988b). On August 9, 1988, EPA sent a letter to the facility stating that Deublin had adequately addressed all violations cited in the April 5, 1988, letter (EPA, 1988b).

In April 1988, in an apparent move to change the RCRA status of its facility operations to that of a small-quantity generator, Deublin, through its contractor, Roy F. Weston, Inc. (Weston), submitted to IEPA a closure plan for CSAs A and B (SWMUs 1 and 2) (Weston, 1988). On June 22, 1988, IEPA approved this closure plan (IEPA, 1988). Weston conducted closure activities for CSAs A and B (SWMUs 1 and 2) on October 15, 1988. Sampling for F001 solvents was conducted of the rinsate from washing of the CSAs and all results were below detection limits. Weston submitted a Closure Certification Statement and a Closure Documentation Report to IEPA on January 9, 1989 (Weston, 1989). In a February 1, 1989, letter from IEPA to Deublin, IEPA stated that the closure of CSAs A and B was complete and that the RCRA status of the facility had been changed to that of a small-quantity generator of hazardous waste (IEPA, 1989). The interior of the facility drains to the city sanitary sewer, the exterior of the facility drains to the city storm sewer. The facility did not have any air permits or NPDES outfalls.

PRC found no documentation of CERCLA or underground storage tank (UST) activity at the Deublin facility.

2.6 ENVIRONMENTAL SETTING

This section describes the climate; flood plain and surface water; geology and soils; and ground water in the vicinity of the facility.

2.6.1 Climate

The climate in Northbrook is greatly influenced by Lake Michigan. Winters are cold and snowy, and summers are warm. The average, daily, high temperature in July is 72.2 °F; the average, daily, low temperature in January is 21.1 °F. The average annual temperature is 49.0 °F (USDA, 1979).

The yearly mean precipitation in Northbrook is 33.42 inches. Average snowfall is 38.3 inches, occurring between October and May (USDA, 1979). Annual mean lake evaporation

in the vicinity of Northbrook is about 29.75 inches (U.S. DOC, 1968). The 1-year, 24-hour maximum rainfall in Northbrook is about 2.4 inches (U.S. DOC, 1961). Winds are typically from the north-northeast in winter and from the south in summer. Average wind speeds range from 8.1 to 12.1 miles per hour (U.S. DOC, 1980).

2.6.2 Flood Plain and Surface Water

The Deublin facility is not located in a 100-year flood plain (FEMA, 1990). Drainage at the facility is directed to the Northbrook storm sewer system, which discharges directly to the West Fork of the North Branch of the Chicago River (Chicago River) (PRC, 1993). The Chicago River is located about 0.5 mile east of the facility and eventually discharges into the Sanitary and Ship Canal. The nearest surface water body is an unnamed pond about 0.25 mile east of the facility; this pond is not used for any known activity (USGS, 1980).

2.6.3 Geology and Soils

No facility-specific geological data exists; the following information is drawn from regional data documented by the Illinois State Geological Survey (ISGS). The region is covered by glacial drift ranging in depth from 3 to 250 feet. The glacial drift is underlain by about 320 feet of Silurian Age dolomites. Beneath the dolomites are four Ordovician Age members: Maquoketa shale-dolomite, Galena-Platteville dolomite, St. Peter sandstone, and Oneota dolomite. The St. Peter sandstone is the only significant water-bearing unit of Ordovician age; it lies almost 900 feet below ground surface in the region. Below the Ordovician system is the Cambrian system, which consists of the following three units: Trempealeau dolomite, Franconia sandstone and dolomite, and Ironton-Galesville sandstone. Of the Cambrian units, only the Ironton-Galesville sandstone produces significant quantities of water (ISGS, 1943a). The deeper Mount Simon sandstone formation is also used as a source of water. It is located about 1,900 feet below ground surface in the region.

2.6.4 Ground Water

The unconsolidated glacial drift and the Silurian dolomite formations beneath the facility are hydraulically connected. However, the depth to ground water and ground-water flow direction are unknown. No users of the shallow drift or dolomite aquifers have been identified

within I mile of the facility. All potable water needs are met by water drawn from Lake Michigan.

The deep sandstones (St. Peter, Ironton-Galesville, and Mount Simon) were once used by industries in the Northbrook and Chicago area. These aquifers are hydraulically separated from the shallow drift and dolomite aquifers by the Maquoketa Shale Formation. Because of local pumping effects, the ground-water flow direction in these units beneath the facility is unknown. The water from these units is generally high in dissolved solids, chloride, sulphate, and hardness (ISGS, 1943b).

2.7 RECEPTORS

The Deublin facility is located on about 80,000 square feet of land in a light to medium-use industrial area in Northbrook, Cook County, Illinois. According to 1990 census data, the population of Northbrook is 33,208 (PRC, 1993).

Deublin is bordered in all directions by industrial facilities. To the north is the Maurice Company across Stanley Street; to the east is Agrimerica, Inc.; to the south is the Illinois Department of Transportation facility and the MagneCraft Company; and to the west is the Robco Company. The nearest residence is located about 0.25 mile west of the facility. The nearest schools are located about 0.5 mile southwest and 0.5 miles west of the facility (USGS, 1980).

Facility access is only partially limited by a chain-link fence that surrounds the parking lot on the eastern side of the facility. The rest of the facility remains locked, and a burglar alarm to detect unauthorized entry has been installed.

The nearest surface water body is an unnamed pond about 0.25 mile east of the facility. This pond is not used for any known purpose. The Chicago River is located about 0.5 mile east of the facility and is used for recreational and wastewater discharge purposes. Lake Michigan lies about 3 miles east of the facility (USGS, 1972).

Ground water is not used as a source of drinking water in the area, and no wells are located in the area.

No sensitive environments are located on site. However, wetland areas greater than 2 acres in size are located within 1 mile northeast of the facility (USGS, 1972).

3.0 SOLID WASTE MANAGEMENT UNITS

This section describes the six SWMUs identified during the PA/VSI. The following information is presented for each SWMU: description of the unit, dates of operation, wastes managed, release controls, history of documented releases, and PRC's observations. Figure 2 shows the SWMU locations.

SWMU 1

Container Storage Area A

Unit Description:

This unit is an unmarked area on the concrete floor of the facility building. The area measures about 19 by 6 feet and is located at the southern end of the loading dock area. Hazardous wastes were stored in containers in this unit until its closure in 1989. The unit had no form of release control other than the facility walls and concrete floors.

Date of Startup:

This unit began operation in 1980.

Date of Closure:

This unit was RCRA-closed on February 1, 1989.

Wastes Managed:

This unit stored containers of waste still bottoms (D001 and F001), waste coolants (D001), waste oil (D001), and waste lapping sludge (D001). These wastes were ultimately shipped off site for treatment or disposal. Hazardous wastes were stored in this unit for more than 90 days until 1983 and were stored for less than 90 days until RCRA-closure in 1989.

Release Controls:

Hazardous wastes were stored in closed containers located indoors on a concrete floor. No other release controls were employed.

History of

Documented Releases:

No releases from this unit have been documented.

Observations:

At the time of the VSI, this unit had been closed, and the facility was no longer in operation. No floor drains or cracks were visible

in the concrete floor. No evidence of release was noted (see Photograph No. 10).

SWMU 2

Container Storage Area B

Unit Description:

This unit is an unmarked area on of the concrete floor of the facility building. The area measures about 16 by 12 feet and is located near the southern end of the loading dock area and under an adjacent stairwell. Hazardous wastes were stored in containers in this unit until its closure in 1989. The unit had no form of release control other than the facility walls and concrete floors.

Date of Startup:

This unit began operation in 1980.

Date of Closure:

This unit was closed on February 1, 1989.

Wastes Managed:

This unit stored containers of waste still bottoms (D001 and F001), waste coolants (D001), waste oil (D001), and waste lapping sludge (D001). These wastes were ultimately shipped off site for treatment or disposal. Hazardous wastes were stored in this unit for more than 90 days until 1983 and were stored for less than 90 days until RCRA-closure in 1989.

Release Controls:

Hazardous wastes were stored in closed containers located indoors on a concrete floor. No other release controls were employed.

History of

Documented Releases:

No releases from this unit have been documented.

Observations:

At the time of the VSI, this unit had been closed, and the facility was no longer in operation. No floor drains or cracks in the concrete floor were visible. No evidence of release was noted (see Photographs No. 7 and 8).

SWMU 3

Container Storage Area C

Unit Description:

This unit is an unmarked area on the concrete floor of the facility building. The area measures about 6 by 24 feet and is located near the northern end of the building next to the small loading dock area. Hazardous wastes were stored in containers in this unit until the facility ceased operations on December 7, 1992. The unit had no form of release control other than the facility walls.

Date of Startup:

This unit began operation in 1988.

Date of Closure:

This unit became inactive on December 7, 1992.

Wastes Managed:

This unit stored containers of waste still bottoms (D001 and F001), waste coolants (D001), waste oil (D001), and waste lapping sludge (D001). These wastes were ultimately shipped off site for treatment or disposal. Hazardous wastes were stored in this unit for less than 90 days.

Release Controls:

Hazardous wastes were stored in closed containers located indoors on a concrete floor. No other release controls were employed.

History of

Documented Releases:

No releases from this unit have been documented.

Observations:

At the time of the VSI, this unit was inactive and the facility was no longer in operation. No floor drains were in the vicinity of this SWMU. Several cracks in the concrete floor were visible. No evidence of release was noted (see Photographs No. 1, 2, and 3).

SWMU 4

Degreaser and Still

Unit Description:

This unit consisted of a vapor Degreaser and an attached Still. The Degreaser has a capacity of 140 gallons. Solvents were used in the degreaser to degrease machined parts. When the solvents became

contaminated, they were cycled through the Still for cleaning and then pumped back into the Degreaser. Still bottoms (D001 and F001) were removed from the Still, drummed, and placed in one of the three CSA (SWMUs 1, 2, and 3). Hazardous wastes were not stored at SWMU 4.

Date of Startup:

This unit began operation in 1981.

Date of Closure:

This unit became inactive on December 7, 1992.

Wastes Managed:

This unit managed waste still bottoms (D001 and F001). These wastes were drummed; stored in CSA A, B, or C (SWMU 1, 2, or 3); and ultimately shipped off site for treatment or disposal.

Release Controls:

This unit was located on the concrete floor inside the facility building. It had no other forms of release control.

History of

Documented Releases:

No releases from this unit have been documented.

Observations:

This unit was inactive at the time of the VSI. The Degreaser and Still had been moved from their original location to a location along the northern wall in the eastern machine shop area. No floor drains or cracks in the concrete floor were visible. PRC noted no evidence of release (see Photographs No. 4, 5, and 11).

SWMU 5

Scrap Metal Accumulation Area

Unit Description:

This unit is an area on the concrete floor of the facility building. It is located adjacent to the loading dock near the western end of the building. Scrap metal generated from cutting and trimming operations was stored in drums in this unit to await pickup by a scrap metal hauler. Hazardous wastes were not stored at this location.

Date of Startup:

It is not known when this unit began operation.

Date of Closure:

This unit ceased operation on December 7, 1992.

Wastes Managed:

This unit managed and stored nonhazardous scrap metal.

Release Controls:

This unit is located on the concrete floor of the facility building. It

has no other forms of release control.

History of

Documented Releases:

No releases from this unit have been documented.

Observations:

This unit was inactive at the time of the VSI. PRC noted no

evidence of release (see Photograph No. 6).

SWMU 6

Coolant Reclamation Unit

Unit Description:

This unit consisted of two interconnected, 250-gallon tanks used for recycling of waste machine coolants. Waste coolants (D001) were processed through these tanks, and waste coolant, oil, metal fines, and shop dirt were separated out from the recycled coolant. The waste coolants were then drummed and immediately transferred to one of the three CSAs (SWMUs 1, 2, and 3). Hazardous wastes were not stored in this area.

Date of Startup:

This unit began operation in 1983.

Date of Closure:

This unit became inactive on December 7, 1992.

Wastes Managed:

This unit managed waste coolants (D001) These wastes were drummed, stored in one of the three CSAs (SWMUs 1, 2, and 3), and ultimately shipped off site for treatment or disposal.

Release Controls:

This unit was located on the concrete floor inside the facility building. It had no other forms of release controls.

History of

Documented Releases:

No releases from this unit have been documented.

Observations:

The two tanks were no longer in place at the time of the VSI. PRC noticed moisture stains along the wall next to the SWMU area, but it was determined that these stains were the result of water seepage. PRC noticed no evidence of release (see Photograph No. 9).

4.0 AREAS OF CONCERN

PRC identified no AOCs during the PA/VSI.





5.0 CONCLUSIONS AND RECOMMENDATIONS

The PA/VSI identified six SWMUs and no AOCs at the Deublin facility. Background information on the facility's location; operations; waste generating processes and waste management practices; history of documented releases; regulatory history; environmental setting; and receptors is presented in Section 2.0. SWMU-specific information, such as the unit's description, dates of operation, wastes managed, release controls, history of documented releases, and observed condition, is presented in Section 3.0. AOCs are discussed in Section 4.0. Following are PRC's conclusions and recommendations for each SWMU. Table 3, located at the end of this section, summarizes the SWMUs and AOCs at the facility and the recommended further actions.

SWMU 1

Container Storage Area A

Conclusions:

RCRA closure of this unit was approved by IEPA in 1989. The unit has been inactive since 1989. This unit was located indoors on a concrete floor. The unit has no documented release history. The potential for release to all environmental media is low.

Recommendations:

PRC recommends no further action at this time.

SWMU 2

Container Storage Area B

Conclusions:

RCRA closure of this unit was approved by IEPA in 1989. The unit has been inactive since 1989. This unit was located indoors on a concrete floor. The unit has no documented release history. The potential for release to all environmental media is low.

Recommendations:

PRC recommends no further action at this time.

SWMU 3

Container Storage Area C

Conclusions:

This unit has been inactive since December 7, 1992. This unit is located indoors on a concrete floor. The unit has no history of documented releases, and no evidence of release was noted during the VSI. The potential for release to all environmental media is low.

Recommendations:

PRC recommends no further action at this time.

SWMU 4

Degreaser and Still

Conclusions:

This unit has been inactive since December 7, 1992. This unit is located indoors on a concrete floor. The unit has no history of documented releases, and no evidence of release was noted during the VSI. The potential for release to all environmental media is low.

Recommendations:

PRC recommends no further action at this time.

SWMU 5

Scrap Metal Accumulation Area

Conclusions:

This unit has been inactive since December 7, 1992. This unit is located indoors on a concrete floor. The unit has no history of documented releases, and no evidence of release was noted during the VSI. The potential for release to all environmental media is low.

Recommendations:

PRC recommends no further action at this time.

SWMU 6

Coolant Reclamation Unit

Conclusions:

This unit has been inactive since December 7, 1992. This unit is located indoors on a concrete floor. The unit has no history of documented releases, and no evidence of release was noted during the VSI. The potential for release to all environmental media is low.


Recommendations:

PRC recommends no further action at this time.

RELEASED 100

RIN #

INITIALS WV



ENFORCE ENT ONFIDE AL

TABLE 3 SWMU SUMMARY

	SWMU	Dates of Operation	Evidence of Release	and the second of the second	mmended ner Action
1.	CSA A	1980 to February 1, 1989	None	None	
2.	CSA B	1980 to February 1, 1989	None	None	RELEASED 0
3.	CSA C	1988 to December 7, 1992	None	None	RIN #/
4.	Degreaser and Still	1981 to December 7, 1992	None	None	
5.	Scrap Metal Accumulation Area	Unknown to December 7, 1992	None	None	
6.	Coolant Reclamation Unit	1983 to December 7, 1992	None	None	

REFERENCES

- Deublin Company (Deublin), 1980a. Notification of Hazardous Waste Activity Form, August 26.
- Deublin, 1980b. Part A Permit Application, October 8.
- Deublin, 1983. Letter from Carl L. Birkenstock to EPA, June 8.
- Deublin, 1988a. Plant Layout, April.
- Deublin, 1988b. Letter from Richard Shipway to Paul Dimock, EPA, May 4.
- Federal Emergency Management Agency (FEMA), 1990. Flood Boundary and Floodway Map for Northbrook, Illinois, December 15.
- Illinois Environmental Protection Agency (IEPA), 1982. Letter from Kenneth Becheley to Jack Falls, Deublin, March 9.
- IEPA, 1988. Closure Plan Approval Letter from Lawrence Eastep to Richard Shipway, Deublin, June 22.
- IEPA, 1989. Letter from Lawrence Eastep to Richard Shipway, Deublin, February 1.
- Illinois State Geological Survey (ISGS), 1943a. Letter from L.E. Workman to Kropp Forge Company, June 10.
- ISGS, 1943b. Letter from William Wrather to H.J. Jirka, Kropp Forge Company, June 15.
- PRC Environmental Management, Inc. (PRC), 1993. Record of Telephone Conversation between Terry Quirk, PRC, and Randy Hayden, Northbrook, Illinois, Department of Public Works, February 11.
- U.S. Department of Agriculture (USDA), 1979. Soil Survey of Du Page and Cook Counties, Illinois, May.
- U.S. Department of Commerce (U.S. DOC), 1961. Rainfall Frequency of the United States, Technical Paper No. 40, U.S. Government Printing Office, Washington, DC.
- U.S. DOC, 1968. Climatic Atlas of the United States, U.S. Government Printing Office, Washington, DC.
- U.S. DOC, 1980. Statistical Abstract of the United States, National Data Book and Guide to Sources, 101st Edition, U.S. Government Printing Office, Washington, DC.
- U.S. Environmental Protection Agency (EPA), 1983. Letter from Karl Klepitsch to Jack Falls, Deublin, May 26.
- EPA, 1984. Letter from Robert Stone to Carl L. Birkenstock, Deublin, May 2.
- EPA, 1988a. Letter from Paul Dimock to Richard Shipway, Deublin, April 5.

REFERENCES

(continued)

- EPA, 1988b. Letter from Paul Dimock to Richard Shipway, Deublin, August 9.
- United States Geological Survey (USGS), 1972. Topographic Map for Park Ridge, Illinois, Quadrangle, 7.5 Minute Series.
- USGS, 1980. Topographic Map for Highland Park, Illinois, Quadrangle, 7.5 Minute Series.
- Roy F. Weston, Inc. (Weston), 1988. Closure Plan for Hazardous Waste Container Area for Deublin Company, April.
- Weston, 1989. Closure Documentation Report for Deublin Company, January 9.

ATTACHMENT A
EPA PRELIMINARY ASSESSMENT FORM 2070-12



POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT PART 1 - SITE INFORMATION AND ASSESSMENT

I. IDENTIFIC	ATION
01 STATE	02 SITE NUMBER

II. SITE NAME AND LOCATION		<u>eni di banda.</u> Kasali bandari	<u>saansa vastaa.</u> Promisionesta		
01 SITE NAME (Legal, common, or descriptive name of site) Deublin Company (Deublin)	02 STREE 1919	02 STREET; ROUTE NO. OR SPECIFIC LOCATION IDENTIFIER 1919 Stanley Street			
03 CITY Northbrook	04 STATE	05 ZIP CODE 60062	06 COUNTY Cook	07 COUNTY CODE	OB CONG DIST
09 COORDINATES: LATITUDE LONGITUDE 42°07'07"N 87°49'39"W					
10 DIRECTIONS TO SITE (Starting from nearest public road) From Interstate 94, take Willow Road west to Shermer Rosacility is on the right.	ad north; proceed	about 1 mile	to Stanley Stre	et and go 1/8	of a mile; the
III. RESPONSIBLE PARTIES					
01 OWNER <i>(if known)</i> Deublin	 4	02 STREET (Business, mailing residential) 2050 Norman Drive West			
03 CITY Waukegan	04 STATE IL	05 ZIP CODE 60085-6747	06 TELEPHONE 708-689-	Account to the first term	
07 OPERATOR (If known and different from owner) Same as above	OB STREE	OB STREET (Business, mailing, residential)			
09 CITY	10 STATE	11 ZIP CODE	12 TELEPHONE	NUMBER	
13 TYPE OF OWNERSHIP (Check one) ELA. PRIVATE D.B. FEDERAL: (Agency Name) (Specify)	□ C. STA □ G. UNK		COUNTY	D E. MUNICIP	AL.
14. OWNER/OPERATOR NOTIFICATION ON FILE (Check all that apply) A. RCRA 3010 DATE RECEIVED: 08/26/80 B. UNCON MONTH DAY YEAR	TROLLED WASTE SIT	E (CERCLA 103 (c/ DATE RECEIV	ED: / / MONTH DAY	
IV. CHARACTERIZATION OF POTENTIAL HAZARD					
O1 ON SITE INSPECTION BY (Check all that apply) A. EPA SE YES DATE 02/01/93 DE. LOCAL HEAL CONTRACTOR NAME(S):PRC			(Spe	. OTHER CONTRA	ACTOR
□ A. ACTIVE □ C.UNKNOWN	<u>195</u>				
04 DESCRIPTION OF SUBSTANCES POSSIBLY PRESENT, KNOWN, OR ALLE Hazardous wastes are no longer managed at this facility.	GED				
05 DESCRIPTION OF POTENTIAL HAZARD TO ENVIRONMENT AND/OR POP	ULATION .				
V. PRIORITY ASSESSMENT					
O1 PRIORITY FOR INSPECTION (Check one. If high or medium is checked, c. L. A. HIGH L. B. MEDIUM L. (Inspection required) (Inspection required) (Inspect		D. NONE		ion of Hazardous omplete current di	
VI. INFORMATION AVAILABLE FROM			CC		-position (UIII)
01 CONTACT 02 OF (Agency, Kevin Pierard EPA	/Organization)				03 TELEPHONE NUMBER (312) 886-4448
04 PERSON RESPONSIBLE FOR ASSESSMENT 05 AGENCY Terry Quirk	06 ORG	ANIZATION PRC	07 TELEPHONE 312/8	E NUMBER 56-8700	08 DATE 02/01/93
FPA FORM 2070.12(17.81)					MONTH DAY YEAR

ATTACHMENT B
VISUAL SITE INSPECTION SUMMARY AND PHOTOGRAPHS

VISUAL SITE INSPECTION SUMMARY

Deublin Company 1919 Stanley Street Northbrook, Illinois 60062 ILD 005 180 195

Date:

February 1, 1993

Primary Facility Representative: Representative Telephone No.:

Richard T. Shipway, Plant Manager, Deublin Company 708-689-8600

Inspection Team:

Terry Quirk, PRC Environmental Management, Inc. (PRC) John Grabs, PRC

Photographer:

John Grabs

Weather Conditions:

Clear, 35 °F

Summary of Activities:

The visual site inspection (VSI) began at 8:30 a.m. with an introductory meeting. The inspection team explained the purpose of the VSI and the agenda for the visit. The facility representative then discussed the facility's past and current operations, solid wastes generated, and release history. The facility representative provided the inspection team with copies of requested documents.

The VSI tour began at 9:35 a.m. PRC inspected the facility building and all solid waste management units (SWMU), including container storage area (CSA) A (SWMU 1), CSA B (SWMU 2), CSA C (SWMU 3), the Degreaser and Still (SWMU 4), the Scrap Metal Accumulation Area (SWMU 5), and the Coolant Reclamation Unit (SWMU 6). All the SWMUs were located within the facility building.

The tour concluded at 10:08 a.m., after which the inspection team held an exit meeting with the facility representative. The VSI was completed and the inspection team left the facility at 10:30 a.m.



Photograph No. 1 Orientation: North Description: CSA C

Location: SWMU 3 Date: 02/01/93



Photograph No. 2 Orientation: North Description: CSA C Location: SWMU 3 Date: 02/01/93



Photograph No. 3 Orientation: North Description: CSA C

Location: SWMU 3 Date: 02/01/93



Photograph No. 4 Orientation: Northeast

Description: Degreaser and Still (current locations)

Location: Northern wall Date: 02/01/93



Photograph No. 5 Orientation: North

Description: Degreaser and Still (current location)

Location: Northern wall Date: 02/01/93



Photograph No. 6 Orientation: West

Description: Scrap Metal Accumulation Area

Location: SWMU 5 Date: 02/01/93



Photograph No. 7 Orientation: South Description: CSA B

Location: SWMU 2 Date: 02/01/93



Photograph No. 8 Orientation: South Description: CSA B Location: SWMU 2 Date: 02/01/93



Photograph No. 9 Orientation: Northeast

Description: Coolant Reclamation Unit

Location: SWMU 6 Date: 02/01/93



Photograph No. 10 Orientation: Southeast Description: CSA A Location: SWMU 1 Date: 02/01/93



Location: SWMU 4 Date: 02/01/93

Photograph No. 11
Orientation: North
Description: Former location of Degreaser and Still


ATTACHMENT C
VISUAL SITE INSPECTION FIELD NOTES

Dluggs Small gount merch 24 drums/yl Layping 5/00/5 , Tomsok (wat word offer 1987 TCA+ From used socrety 10 cm 5 16 11 1 Douglook Fren 1 com 83 10 88 U &ed TCA +0 1483 Won Lynday 1, 1967 Door , cothy oils 104 J. Her 128 IN Debuccion 1) Mon Gebrary 1, 1997 5/17 6, 1897 (1984) 5/17 6, 189 5 4 4 4 4 5 8 × × × (5 6 / 1) 5 5 × × × (5 6 / 1) 5 Mfy (6 Pahrs priors) Stands bass, elumpum plan. July Lad Lassina (He 7 1492 to 2050 2050) 36,000 Sq Ret at THU Vaular 200 600 85 0.0 px+3-80,000ft mach a of 1 3 colings. JUST Closed, moud ac| (1+1-1

120 Sen 28 Bo Storm Chance Slayed wing coass At B 5-12 pool 5 chesher 10 1983 5 Hetel Startto crosnd B6 CG) S W & C C Maitenana Room Co greese To Usgales sec 140 gal to his Knowlegel CSIND A FRE Pats claster NO ASTS/USTS SUMUS 2nd+30 Sh. Fts ~10 roge 11.014 d of 3 mus/well Up to 15 drums stored reco (North of Ara B) Mon Kilbroury , HAAA 130 employees when United Series In recolled gotings 5 days/week 101455/(45) 1con Day Stack moved out Cust & Forked DN 0.

duys less then godges come of crack of crack of crack chay 28/5 + then 1,000 * notinglas in the Photo 231 Cusher North Area C CSA veer & inspections def + 181 + 54 !! 6937 (hota 1424) Southers f 100 - 14 SOMO 164 Not the brook from Luke Mich, Runolf to Fitz Storm Somes a wage goes to mining 5 lond dows on 20 all drains in soilding so to no known releases. (1) (de 2) (de 3) Land RIL macky 1.35-5 Ser UST Day jung ロアカ

will read the thing transfer المحرس المركور وددر ما المركور form clesses & SAI Toration Assert SE NO Wages new door (Arry 13 500) Pool Siel Of Or of the 10,30 (eax 51k Jon June + Pros will be senti 47791919 And talk 00 gurs 4.0015 150 +50 1) Ofour El A OHO 10,05 10,08 CYSS Photo 7 waste ocean west object ocean west object ocean west NE & NOT INPOSED A dipms were filled from und 5 24, 15 6 60 541, 05 4150 pho bes 44550-2 5+6 30/11 + tale to CSA no sability accom for 10 coolent acclumn Megresse + SAII SAIL bellems. 2014



Richard T. Shipway

- PRECISION POTATING UNIONS

 SPENIN JOHN'S & SIPHON SYSTEMS

 EXPANDING CORE HOLDING EQUIPMENT
- 2050 NORMAN DRIVE, WEST WALKEGAN, IL 60085 6747 PHONE: 708-689-8600 FAX: 708-689-8690

ACT DYN		/ \ /
listed as	CERTIFICATION REGARDING POTENTIAL RELEASES FRO	My Carl
Dubo	a OP	
FACILITY NAME:	DEUBLIN COMPANY	R R R R R R R R R R R R R R R R R R R
EPA I.D. NUMBER:	ILD005180195	JAN 2 4 1986
LOCATION CITY:	1919 STANELY STREET, NORTHBROOK	SWD - HIS
STATE:	ILLINOIS 60062	U.S. EPA, REGION V
Closed) at your CURRENTLY SHOW! Landfill Surface Importance Land Farm Waste Pile Incinerator Storage Tan Container S Injection W Wastewater Transfer St Waste Recyc Waste Treat Other 2. If there are " provide a desc of in each unit would be consi RCRA. Also in disposed of an of each unit a	((Above Ground) ((Underground) torage Area ells Treatment Units	ove, please or disposed of the wastes ents under e of wastes description

NOTE: Hazardous wastes are those identified in 40 CFR 261. Hazardous constituents are those listed in Appendix VIII of 40 CFR Part 261.


3. For the units noted in Number 1 above and also those hazardous waste units in your Part A application, please describe for each unit any data available on any prior or current releases of hazardous wastes or constituents to the environment that may have occurred in the past or may still be occurring.

Please provide the following information

- a. Date of release
- b. Type of waste released
- c. Quantity or volume of waste released
- d. Describe nature of release (i.e., spill, overflow, ruptured pipe or tank. etc.)



4. In regard to the prior or continuing releases described in Number 3 above, please provide (for each unit) any analytical data that may be available which would describe the nature and extent of environmental contamination that exists as a result of such releases. Please focus on concentrations of hazardous wastes or constituents present in contaminated soil or groundwater.



I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the submittal is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations. (42 U.S.C. 6902 et seq. and 40 CFR 270.11(d))

JACK E. FALLS, PLANT MANAGER

Typed Name and Title

Signature

JAN-22-86





SEPT. 10-1980

BACK OF BUILDING AND EAST

END.

FROM 9/E CORNER OF PROPERTY.

SEPT, 10-1980

FRONT OF BUILDING FROM.

N/W CORNER OF PROPERTY





SEPT. 10-1980

RECEIVING DOCK.

WEST END OF BUILDING.

FROM N/W. CORNER OF PROPERTY

SEPT, 10 1980.

RECEIVING DOCK AREA TO BE
USED TO STORE DRUMS OF

CHLOROETHENE NU